

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20012554/R1VF3E2

Date: 18/12/2020

REFERENCE

Insured/Claimant:	PATRAWALA ABBAS AKBAR	Policy No:	1900103419	
Date of Loss:	13/11/2020	Nature of Claim:	OD	Claim No: 5039723005SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM2519K	Engine No:	3A92UHS9539
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AKH001830
Reg. Date:	24/06/2019 (Man. Year: 2019)	Odometer:	14952 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$52,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,240.57	6,117.14	1,123.43	15.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,500.00	8,065.00	2,435.00	23.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,740.57	14,182.14	3,558.43	20.06
+ GST 7.00/7.00% (S\$)	1,241.84	992.75	249.09	20.06
Nett Amount (S\$)	18,982.41	15,174.89	3,807.52	20.06

INSPECTION

Date of Assignment: 16/11/2020

Date Inspected: 16/11/2020 Inspected At:

Estimated Period of Repair: 14.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE WITH FRAME	Scratched	50.00 FS	*50.00 FS
2	1		*PARKING SENSOR	Not Working	220.00 FS	*220.00 FS
3	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
4	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
5	1		*BODY KIT ATTRAGE, TITANLUM GREY, U17	Deformed	1,643.00 FS	*1,643.00 FS
6	1		*FACE, RR BUMPER	Deformed	748.00 FL	*748.00 FL
7	1		*BRACKET, RR BUMPER, RH	Broken	28.00 FL	*28.00 FL
8	1		*BRACKET, RR BUMPER, LH	Broken	28.00 FL	*28.00 FL
9	1		*PANEL, TRUNK LID	Bent	791.00 FL	*791.00 FL
10	1		*HINGE, TRUNK LID, RH	Serviceable	203.00 FL	*- FL
11	1		*HINGE, TRUNK LID, LH	Serviceable	203.00 FL	*- FL
12	1		*WEATHERSTRIP, TRUNK LID	Serviceable	157.00 FL	*- FL
13	1		*LATCH, TRUNK LID	Bent	218.00 FL	*218.00 FL
14	1		*STRIKER, TRUNK LID LATCH	Serviceable	20.00 FL	*- FL
15	2		*STOPPER, WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
16	3		*SPACER, RR WINDOW	Necessary	27.00 FL	*27.00 FL
17	1		*PANEL, RR END	Bent	425.00 FL	*425.00 FL
18	1		*MUD GUARD, RR LH	Not Necessary	41.00 FL	*- FL
19	1		*MUD GUARD, RR RH	Not Necessary	41.00 FL	*- FL
20	1		*PANEL, QTR, OTR RH	Bent	763.00 FL	*763.00 FL
21	1		*PANEL, QTR, OTR LH	Bent	755.00 FL	*755.00 FL
22	1		*PANEL, RR COMB LAMP HSG, RH	Missing	60.00 FL	*60.00 FL
23	1		*PANEL, RR COMB LAMP HSG, LH	Missing	60.00 FL	*60.00 FL
24	1		*EXTN, QTR PANEL, UPR OTR LH	Serviceable	118.00 FL	*- FL
25	1		*EXTN, QTR PANEL, UPR OTR, RH	Serviceable	118.00 FL	*- FL
26	1		*GARNISH, RR END PANEL	Deformed	336.00 FL	*336.00 FL
27	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
28	1		*MARK, ATTRAGE	Necessary	21.00 FL	*21.00 FL
29	1		*TRIM, RR END	Serviceable	66.00 FL	*- FL
30	1		*BOARD, TRUNK ROOM FLOOR	Cracked	195.00 FL	*195.00 FL
31	1		*TRIM, TRUNK ROOM SIDE, RH	Serviceable	160.00 FL	*- FL
32	1		*TRIM, TRUNK ROOM SIDE, LH	Serviceable	160.00 FL	*- FL
33	1		*REFLECTOR LH	Serviceable	23.00 FL	*- FL
34	1		*REFLECTOR RH	Serviceable	23.00 FL	*- FL
35	1		*LAMP ASSY, COMB, RR RH	Cracked	335.00 FL	*335.00 FL
36	1		*LAMP ASSY, COMB, RR LH	Cracked	335.00 FL	*335.00 FL
37	1		*LAMP ASSY, LICENSE PLATE	Broken	51.00 FL	*51.00 FL
38	1		*ANT, KEYLESS OPERATION, RR	Serviceable	96.00 FL	*- FL
39	1		*COVER, RR VENTILATOR	Broken	40.00 FL	*40.00 FL
40	1		*DUCT, RR VENTILATOR	Serviceable	30.00 FL	*- FL
41	1		*BUZZER, KEYLESS OPERATIO, RR	Broken	91.00 FL	*91.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,814.00	7,355.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,573.43	1,237.86
Total Parts (\$\$)	7,240.57	6,117.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR AIRDAM, REAR BUMPER, REAR END PANEL, BOOTLID REAR LAMP HOUSING RH & LH, REAR FENDER LH & RH, REPAIR REAR COMPARTMENT	New	5,400.00	4,500.00
2	REMOVE & INSTALL SPOILER	New	100.00	80.00
3	REMOVE & INSTALL REAR AIRDAM	New	100.00	80.00
4	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
5	SPRAY PAINT FOR REAR AIRDAM, REAR BUMPER, REAR END PANEL, REAR COMPARTMENT, REAR FENDER RH & LH, REAR LAMP HOUSING RH & LH BOOTLID,	New	3,150.00	2,450.00
6	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	300.00	120.00
7	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	80.00
10	REMOVE & INSTALL FUEL TANK	New	480.00	225.00
11	REMOVE & INSTALL REAR WINDSCREEN	New	240.00	240.00
12	APPLY SEALANT FOR REAR WINDSCREEN	New	80.00	80.00
13	REMOVE & INSTALL REAR FENDER TRIMS, SEATS	New	360.00	0.00
Gross Labour Cost (\$\$)			10,500.00	8,065.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >