

GX5302L

Toyota Liteace

CR42500T273

TP Budget Direct.

Xiao Chen

Rear Bumper	Deformed	375.50 ✓
Rear Bumper Clips.	N/A	30(SN) ✓
Rear Bumper Side Holder	x 02 N/A	81.1 x 2 = 162.20 ✓
Rear Bumper Reflector LH.	Crushed	47.60 ✓
Reverse Sensor	Damaged	280(SN) 220(SN)
Rear End Panel Outer.	Dented	561.40 ✓
Rear End Panel Inner.	Repair	371.50 +
Rear End Panel Top Garnish	N/A	182.20 +
Rear End Panel Sealant.	N/A	60(SN) ✓
Tailgate.	Repair	1050 +
Tailgate Lock	} new	289.90 +
Tailgate Weatherstripe		282.90 +
Tailgate Glass Moulding	} new	171 +
Tailgate Glass Sealant.		60(SN) +
70km/h Sticker	} new	15(SN) ✓
5px Sticker.		15(SN) ✓

GX5302L.

Rear Exhaust Pipe. Best. 781.10 LR (120).

Rear Exhaust Mounting. ^{MP}_m 36.50 X.

Panel Beating. ~~900~~ 600

Spray Painting. ~~800~~ 500.

Wiring. ~~50~~ 30

To remove reverse sensor ~~100~~ 60

To remove upholstery. ~~150~~ 80

To remove tailgate glass. 180 X

To transfer tailgate fittings. 150 X

To remove exhaust pipe. ~~150~~ 80

To spray tuff coat. ~~150~~ 80

hist. 1146.70

km 25%: 860.02

S.N: A60

Labour: 11430

total: 275002

L/S: 2.2K.

04 Days.

2.214