

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012559/KBS3Q2

Date: 12/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100367985
Claimant Vehicle No :	SJF9177P	Insured Vehicle No :	SGV2248R
Date of Loss:	11/11/2020	Nature of Claim:	TP
		Claim No:	0411153159SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF9177P		
Make & Model:	MITSUBISHI LANCER, 2.0 L MIVEC GLS6-CVT (A)	Engine No:	4B11BQ4996
Reg. Date:	16/06/2008 (Man. Year: 2008)	Chassis No:	JMYSTCY4A8U004346
Colour:	White	Odometer:	343610 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Michelin 2 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Michelin 2 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,657.75	2,140.10	517.65	19.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,400.00	880.00	38.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,937.75	3,540.10	1,397.65	28.31
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	4,937.75	2,800.00	2,137.75	43.29
+ GST 7.00/7.00% (S\$)	345.64	196.00	149.64	43.29
Nett Amount (S\$)	5,283.39	2,996.00	2,287.39	43.29
+ Car Rental (7.0 x S\$120.00/day + 7.00% GST) (S\$)		898.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,896.80		
Global Sum Settlement (S\$)		3,890.00		

INSPECTION

Date of Assignment: 16/11/2020

Date Inspected: 16/11/2020 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17,
AMK Autopoint
Singapore 568047

5/12/2021

Adjuster Report

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	895.00 FN	*815.00 FN
2	10		*REAR BUMPER CLIPS	Necessary	38.00 FN	*38.00 FN
3	1		*REAR BUMPER REINFORCEMENT	Buckled	232.00 FN	*232.00 FN
4	2		*REAR BUMPER BRACKETS	Repair	35.00 FN	*- FN
5	1		*REAR BUMPER REFLECTOR LH	Cracked	24.00 FN	*24.00 FN
6	1		*REAR BUMPER TOP BEAM	Bent	73.00 FN	*73.00 FN
7	4		*REAR BUMPER CORNER RETAINER RIVETS	Necessary	50.00 FN	*50.00 FN
8	1		*REAR BUMPER INNER BOOT SENSOR	Cracked	145.00 FN	*145.00 FN
9	1		*REAR NUMBER PLATE LAMP	Missing	135.00 FN	*55.00 FN
10	1		*BOOT BADGE 2.0 MIVES	Necessary	55.00 FN	*55.00 FN
11	1		*BOOT BADGE GT	Necessary	46.00 FN	*46.00 FN
12	1		*END PANEL	Bent	556.00 FN	*506.00 FN
13	1		*END PANEL GARNISH	Serviceable	163.50 FN	*- FN
14	1		*REAR BUMPER REVERSE SENSOR	Cracked	280.00 FS	*200.00 FS
15	1		*REAR NUMBER PLATE (CHROME LETTER)	Bent	120.00 FS	*50.00 FS
16	1		*BOOT BADGE C&C	Necessary	55.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	2,902.50	2,344.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	244.75	203.90
Total Parts (\$\$)	2,657.75	2,140.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT REAR ELECTRICAL CHECK ,REPLACE REVERSE SENSORS ,MODULE REWIRING ETC	New	120.00	20.00
2	TO SUPPLY END PANEL BODY SEALANT	New	60.00	30.00
3	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	50.00	30.00
4	TO DISMANTLE /REFIT REAR TRUCK AUDIO POWER AMP ,WOOFER ,CUSTOM MADE BOARD ETC	New	250.00	120.00
5	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF REAR CHASSIS MEMBER,INNER PANEL ,SPARE TYRE PANEL ETC ,CNT ,WELD END PANEL AND PARTS REPLACEMENT	New	900.00	600.00
6	TO RESPRAY AFFECTED AREAS	New	900.00	600.00
Gross Labour Cost (S\$)			2,280.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >