

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 6142X**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER SPORT	DEFORMED / TORN	1,200.00	1,080.00
2	REAR BUMPER RETAINER @\$45.00	NOT NECESSARY	90.00	-
1	REAR BOOT LID	DENTED / BENT	610.70	610.70
2	REAR BOOT REFLECTOR @\$214.70	O/S CRACKED	429.40	214.70
1	TAIL LAMP (LH)	CRACKED	314.40	308.20
1	REAR BOOT INNER LOCK	SERVICEABLE	213.70	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	438.70	-
1	REAR END PANEL GARNISH	NOT NECESSARY	253.40	-
	LESS 20% DISCOUNT		-710.06	-442.72
			2,840.24	1,770.88
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET BUMPER CLIP (SN)	NECESSARY	40.00	30.00
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	200.00
			290.00	230.00
	<b><u>LABOUR</u></b>			
	TO REMOVE, REPLACE REVERSE SENSOR.		80.00	50.00
	TO REMOVE, REPLACE BOOT LID, BUMPER & END PANEL. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		880.00	480.00
	TO SPRAY PAINTING.		800.00	600.00
			1,760.00	1,130.00
	<b>GRAND TOTAL</b>		<b>4,890.24</b>	<b>3,130.88</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,500.00</b>

Report Ref No. CS/UOI20012561/Uqf3e2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.