# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers Correspondence Mail Address: My Mail Box 886259 Singapore 919191 Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

#### VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0350820

Date of Report

: 18/09/2020

To: Mr Chang Chee Heng, Terry (Zhang Qiheng, Terry)

Date of Assignment

: 31/08/2020

C/o. 48 Toh Guan Road East

Report requested by

: Mr Chang Chee Heng, Terry

#01-119 Enterprise Hub

Date of Accident

: 27/08/2020

Singapore 608586

Date of Inspection

: 31/08/2020

Claim No.

: Third Party Claim

Policy No.

#### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SGZ76L

Engine Capacity (cc) : 1986cc

Make & Model

: Toyota Harrier

Mileage (km)

: 63446km

Date of Registration

: 29/07/2016

Chassis / Frame No. : ZSU600078503

Colour

: Met. Black

Engine No.

: 3ZRB784734

#### TYRE CONDITION

Front LH

: 8 mm

Front RH

: 8 mm

Make

: Falken

Make

· Falken

Rear LH

: 8 mm

Rear RH

: 8 mm

Make

: Falken

Make

: Falken

Road wheels Type: Alloy

(The above represents the approximate remaining life of (yre treads)

#### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

: Good

Handbrake

: Serviceable

Footbrake

: Serviceable

Steering

: Serviceable

Apparent Engine Modification

: Nil

#### PLACE OF REPAIRER OFFICE/WORKSHOP

Location

M/s. Gold Autoworks Pte Ltd

48, Toh Guan Road East. #01-119, Enterprise Hub. Singapore 608586

### ASSESSMENT

Repairer's Estimate

Revised Amount

9,389.78 : \$

Less Excess

: \$ 7,968.85

: \$

Recommended Reserve

: \$

6,370.00

(Lump Sum)

Estimated Normal Period of Repairs

: 8 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.

P<sub>AS</sub>

Correspondence Mail Address: My Mail Box 886259 Singapore 919191
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No: SGZ76L

Report No.: PAS/TP/0350820

#### GENERAL REMARKS

WITHOUT PREJUDICE

#### THE ASSIGNMENT

The survey was conducted at M/s. Gold Autoworks Pte Ltd, 48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586.

(Subsequent inspections have been conducted)

#### POINT OF IMPACT

At the rear RH portion.

#### **DAMAGES**

The tailgate, rear bumper, rear end panel, rear floor panel, RHR chassis member, rear fenders, rear exhaust silencer, RH taillamp, etc.

Other parts were also found damaged. (See schedule for details)

#### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$7.968.85.

#### CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$6,370.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly.

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

**MSAAA** 

Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No: SGZ76L

Report No.: PAS/TP/0350820

## APPRAISEMENT SCHEDULE

S	S/No.	Qty	Parts Descriptions	Condition			Repairer's Estimate (S\$)		Our Assessment (S\$)			
	1	1 pc	Tailgate /	Dented			\$	1,302.80		\$	1.302.80	/
	2	2 pcs	Tailgate windscreen side clip R/L	Necessary	\$	10.30	\$	20.60		5	20.60	/
	3	2 pcs	Tailgate windscreen s.spacer R/L	Necessary	\$	12.40	\$	24.80		\$	24.80	1
	4		Tailgate windscreen moulding R/L		\$	40.80	\$	81.60		\$	81.60	/
	5	1 pc	Tailgate windscreen low moulding				\$	58.30		\$	58.30	/
	6	1 pc	Tailgate no.plate garnish assy X/	Refit			\$	220.60		\$	-	
	7	1 pc		Not Necessary			\$	50.20		\$	-	
	8	1 pc	Tailgate emblem (HARRIER)	Necessary			\$	57.80		8	57.80	/
	9	1 pc	Tailgate inner trim X SUC	Refit			\$	453.70		\$	-	
	10		Tailgate inner trim clip	Necessary	\$	2.10	\$	25.20		\$	25.20	/
	11	1 pc	Tailgate lock assy X (SVC	Dented/Damaged			\$	954.00		\$	954.00	X
	12		Tailgate weatherstrip X	Tom/Necessary			\$	353.40		\$	353.40	Χ,
	13		Taillamp RH /	Loop Broken			5	582.30		\$	582.30	480.b
	14		Rr bumper reflector RH	Cracked			\$	62.30		\$	62,30	/
	15	8 pcs	Rr bumper clip / (HXSVC	Necessary	\$	3.80	\$	30.40		\$	30.40	/
	16	2 pcs	Rr bumper retainer R/L / PH/ DO	Necessary	\$	65.00	\$	130.00		8	130.00	65
	17		Rr bumper absorber	Dented/Broken			\$	106.30		\$	106.30	/
	18	I pc	Rr end panel	Dented/Distorted			\$	762.00		\$	762.00	/
	19	1 pc	Rr end panel garnish X 9VC	Refit			\$	343.40		\$	-	25 25
	20	I pc	Rr floor side trim RH 入って	Broken			\$	92.60		\$	92.60	X
	21	1 pc	Rr exhaust silencer X Repair	Dented/Bent			\$	687.40		\$	687.40	X
	22		Rr fender R/L	Dented/Repair				(Refe	labour	no.	3, 7 & 8)	
	23	1 pc	Rr floor panel	Dented/Repair	(Refer labour no. 3, 7				3.7 & 8)			
	24	1 pc	Rr chassis member RH	Dented/Repair				(Refe	labour	110.	3, 7 & 8)	
							\$	6,399.70	_	\$	5.331.80	3077.7
					Less I	Discount: 25%	\$	1,599.93	25%	\$	1.332.95	,
				L	ist Parts Su		\$	4.799.78	- Section - Sect	\$	3.998.85	2308.2
	1	1 pc	Rr bumper (SILK-B STYLING)	Dented/Broken		S/N	\$	1,100.00		\$	1.100.00	/
	2	1 pc	Rr bumper fog lamp XSVC	Broken		S/N	\$	120.00		\$	120.00	
	3		Rr reverse sensor	Dented/Damaged		S/N	\$	200.00		\$	200.00	
	4	1 pc	Rr windscreen sealant	Necessary		S/N	\$	50.00		\$	40.00	
	5	1 pc	Rr end panel sealant /	Necessary		S/N	\$	50.00		\$	40.00	
				Special Nett Sub-Total:			\$	1,520.00		\$	1.500.00	
											1480	
					Par	ts Total :	\$	6,319.78	_	\$	5,498.85	-



## NENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehic	cle No : SGZ76L	Report No. : PAS/TP/0350820					
S/No	Labour Descriptions		Repairer's Estimate (S\$)		Our Assessment (S\$)		
1	To transfer rear windscreen to new tailgate.	S	120.00	\$	120.00		
2	To transfer tailgate component parts to new tailgate. (Include transfer tailgate spoiler & supply sealant/adhesive tape)	S	.180.00	\$	160.00 bc		
3	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	S	120.00	\$	100.00 80		
4	To remove and reinstall electrical wiring system for necessary repairs.  To check rear electrical wiring system.	\$	50.00	\$	50.00 3		
5	To straighten, repair, realign center exhaust pipe and replace exhaust silencer.	\$	120.00	\$	80.00 /		
6	To remove, replace and reinstall rear reverse sensors & control unit.	\$	20.00	\$	20.00		
7	To straighten, repair, realign on affected area and replace damaged parts.	\$	1,200.00	\$	880.00 60		
8	To spray painting, blending on affected and adjacent area.	\$	1,200.00	\$	1,000.00 80		
9	To spray anti-rust coating on new and affected panels.	\$	60.00	S	60.00 /		
	Labour Total:	\$	3,070.00	\$	2,470.00		
			1		1850		
	Total (Parts & Labour):	\$	9,389.78	\$	7,968.85		

#### For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$

357,8,28 re/2 4400

Under normal circumstances, the repairs should be completed within a reasonable period 8 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

Photographs were taken at the time of inspection. 60

6 Dans

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.