

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20012575/UBA3Q2

Date: 16/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070110475

**Claimant**  
**Vehicle No :** SLD3208K **Insured Vehicle No :** GBE537T

Date of Loss: 13/11/2020 Nature of Claim: TP Claim No: 0449734462SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLD3208K</b>		
Make & Model:	TOYOTA HARRIER, 2.0 Elegance (A)	Engine No:	3ZRB748668
Reg. Date:	13/06/2016 (Man. Year: 2015)	Chassis No:	ZSU600074427
Colour:	Black	Odometer:	98451 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,292.40	2,504.55	5,787.85	69.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,420.00	950.00	40.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,662.40</b>	<b>3,924.55</b>	<b>6,737.85</b>	<b>63.19</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>(S\$)</b>	10,662.40	3,100.00	7,562.40	70.93
<b>+ GST 7.00/7.00% (S\$)</b>	746.37	217.00	529.37	70.93
<b>Nett Amount (S\$)</b>	<b>11,408.77</b>	<b>3,317.00</b>	<b>8,091.77</b>	<b>70.93</b>
<b>+ Car Rental (4.0 x S\$150.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,919.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,770.00</b>		

### INSPECTION

Date of Assignment: 16/11/2020

Date Inspected: 16/11/2020 Inspected At:

 Fastech Auto Pte Ltd (HQ)  
 1 Kaki Bukit Ave 6, #01-46/48/50  
 Autobay  
 Singapore 417883

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER O/S	Badly Dented	1,866.20 F	*1,255.10 FL
2	1		*REAR FENDER GLASS O/S	Not Necessary	650.00 F	*- FL
3	1		*REAR FENDER UNDER COVER O/S	Torn	488.20 F	*408.10 FL
4	1		*SET REAR FENDER UNDER COVER CLIPS O/S	Necessary	50.00 F	*50.00 FL
5	1		*REAR FENDER INNER TRIM BOARD O/S	Not Necessary	866.20 F	*- FL
6	1		*REAR BUMPER	Deep Cut	1,466.10 F	*955.10 FL
7	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	89.50 F	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
9	1		*TAILLAMP O/S	Cracked	1,066.20 F	*581.10 FL
10	1		*REAR SPORT RIM O/S	Not Necessary	1,650.00 F	*- FL
11	1		*REAR FENDER GLASS SEALANT O/S	Necessary	50.00 FS	*30.00 FS
					<b>Sub Total (\$\$)</b>	<b>8,292.40      3,329.40</b>
					<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00      824.85</b>
					<b>Total Parts (\$\$)</b>	<b>8,292.40      2,504.55</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR BUMPER REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR FENDER GLASS	New	120.00	60.00
4	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
6	TO SPRAY RUST PROOFING	New	50.00	30.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	900.00	600.00
8	TO PUTTY & SPRAY PAINTING	New	900.00	580.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,370.00</b>	<b>1,420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >