

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI20012578/ATF3E2

**Date:** 03/12/2020

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SLL7030L

**Insured Vehicle No :** GBC6312X

Date of Loss: 14/11/2020

Nature of Claim: TP

Claim No: CDMCG20001671

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL7030L**

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: LEB5916635

Reg. Date: 07/03/2017 (Man. Year: 2016)

Chassis No: RU31216622

Colour: Bronze

Odometer: 208057 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,586.00	6,614.88	1,971.12	22.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	2,190.00	1,440.00	39.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,216.00</b>	<b>8,804.88</b>	<b>3,411.12</b>	<b>27.92</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,050.00</b>		
<b>(S\$)</b>	12,216.00	7,050.00	5,166.00	42.29
<b>+ GST 7.00/7.00% (S\$)</b>	855.12	493.50	361.62	42.29
<b>Nett Amount (S\$)</b>	<b>13,071.12</b>	<b>7,543.50</b>	<b>5,527.62</b>	<b>42.29</b>

### INSPECTION

Date of Assignment: 16/11/2020

Date Inspected: 17/11/2020 Inspected At:

Modern Automotive Pte Ltd (HQ)  
Blk 3023A Ubi Road 1, #01-61 & #01-58  
Singapore 408717

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Dec 2020)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLL7030L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP - LH & RH	Not Necessary	77.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	880.00 FL	*880.00 FL
3	2		*REAR BUMPER SIDE HOLDER - LH / RH	Necessary	47.00 FL	*47.00 FL
4	2		*REAR BUMPER SIDE REFLECTOR - LH & RH	Not Necessary	282.20 FL	*- FL
5	1		*REAR BUMPER UNDER COVER	Deformed	285.00 FL	*285.00 FL
6	1		*REAR END PANEL	Dented	585.00 FL	*585.00 FL
7	1		*REAR END PANEL TOP GARNISH	Cracked	98.40 FL	*98.40 FL
8	1		*REAR END PANEL BUZZER	Damaged	85.20 FL	*85.20 FL
9	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	60.10 FL	*- FL
10	2		*TAIL LAMP - LH & RH	Cut	949.20 FL	*949.20 FL
11	2		*TAIL LAMP LOWER APRON - LH & RH	Repair	390.00 FL	*- FL
12	1		*TAILGATE	Distorted	1,100.00 FL	*1,100.00 FL
13	1		*TAILGATE LOCK	Damaged	182.50 FL	*182.50 FL
14	1		*TAILGATE LOCK SWITCH	Damaged	241.40 FL	*241.40 FL
15	1		*TAILGATE OUTER GARNISH	Cracked	325.00 FL	*325.00 FL
16	2		*TAILGATE REFLECTOR - LH & RH	N/S Cut / O/S Cracked	826.40 FL	*826.40 FL
17	1		*TAILGATE INNER TRIM BOARD	Deformed	285.60 FL	*285.60 FL
18	1		*TAILGATE GLASS MOULDING	Necessary	121.00 FL	*121.00 FL
19	1		*HONDA LOGO	Necessary	35.40 FL	*35.40 FL
20	1		*VEZEL EMBLEM	Necessary	45.90 FL	*45.90 FL
21	1		*HYBRID EMBLEM	Necessary	75.80 FL	*75.80 FL
22	1		*REAR FENDER INNER TRIM BOARD	N/S Deformed	590.00 FL	*295.00 FL
23	2		*REAR FENDER INNER SHIELD	Not Necessary	295.00 FL	*- FL
24	1		*SPARE TYRE PANEL TOP COVER	Deformed	306.60 FL	*306.60 FL
25	1		*REAR EXHAUST PIPE	Not Necessary	598.60 FL	*- FL
26	1		*REAR EXHAUST MOUNTING	Not Necessary	28.50 FL	*- FL
27	1		*TAILGATE WEATHERSTRIPE	Cut	135.70 FL	*135.70 FL
28	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
29	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
30	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
31	1		*REAR BUMPER TOP GARNISH	Necessary	150.00 FS	*120.00 FS
32	1		*SET REAR BUMPER UNDER COVER CLIPS	Necessary	30.00 FS	*30.00 FS
33	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
34	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
35	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
36	2		*TAIL LAMP SPONGE GASKET	Necessary	40.00 FS	*40.00 FS
37	1		*SET TAILGATE OUTER GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
38	2		*TAILGATE REFLECTOR SPONGE GASKET	Necessary	40.00 FS	*40.00 FS
39	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
41	1		*REAR CAMERA	Damaged	480.00 FS	*380.00 FS
42	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*60.00 FS
43	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,372.50</b>	<b>7,996.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,786.50	1,381.22
<b>Total Parts (\$\$)</b>	<b>8,586.00</b>	<b>6,614.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,300.00	800.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,300.00	900.00
3	TO CHECK WIRING SYSTEM	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO SPRAY TUFF COAT	New	150.00	80.00
7	TO REMOVE UPHOLSTERY	New	150.00	80.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE REAR EXHAUST PIPE	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,630.00</b>	<b>2,190.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >