Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20012586/DPS3Q2

**Date:** 12/03/2021

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant FRE80864 Insured Vehicle No: SHA6115M

Vehicle No: FBE8086A Insured Vehicle No: SHA6115M

Date of Loss: 11/11/2020 Nature of Claim: TP Claim No: MCT20110191

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBE8086A

 Make & Model:
 YAMAHA SPARK, 135cc
 Engine No:
 5YP302809

 Reg. Date:
 16/09/2010 (Man. Year: 2010)
 Chassis No:
 5YP302809

 Colour:
 Blue/Black
 Odometer:
 22238 km

Engine Capacity: 135 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 70/90R17 Rear Tyre Size: 80/90 R17
Front Left Side: Dunlop 2 mm Rear Left Side: Dunlop 2 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,291.80	2,894.55	1,397.25	32.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	920.00	490.00	430.00	46.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,211.80	3,384.55	1,827.25	35.06
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	5,211.80	2,700.00	2,511.80	48.19
+ Loss of Use (5.0 x S\$2	20.00/day) (S\$)	100.00		
+ Ot	120.00			
Net	tt Liability (S\$)	2,920.00		
Global Sum S	ettlement (S\$)	2,920.00		

**INSPECTION** 

Date of Assignment: 16/11/2020

Date Inspected: 17/11/2020 Inspected At: S9 Motor Trading Pte Ltd (HQ)

4001 ANG MO KIO INDUSTRÍAL

PARK 1 #01-21 Singapore 569622

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI Manager: CHEW HSIAO TONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

## REPAIR DETAILS

Reference
Part Source: (Last Synchronised: 04 Feb 2021)

Parts: N/A YAMAHA SPARK 135cc (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBE8086A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Repairer's

**Amount** 

2,894.55

4,291.80

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts No. Qtv Part No. Particulars

NO.	Qty	Part NO.	Particulars	Condition	Repairer 5	Amount	
1	1		*HANDLE BAR	Bent	165.00 FL	*165.00 FL	
2	1		*HANDLE BAR BRACKET	Bent	125.00 FL	*125.00 FL	
3	1		*SET STEERING CONE BEATING	Serviceable	125.00 FL	*-FL	
4	1		*HEAD LAMP	Cut	320.00 FL	*320.00 FL	
5	1		*HEAD LAMP TOP COVER	Broken	135.00 FL	*135.00 FL	
6	1		*MIRROR	O/S Broken/CutN/SNot Necessary	125.00 FL	*62.50 FL	
7	1		*BRAKE LEVER	Cut	68.00 FL	*68.00 FL	
8	1		*METER COVER REAR	Broken	195.00 FL	*195.00 FL	
9	1		*LEG SHIELD -TOP COVER	Broken	178.00 FL	*178.00 FL	
10	1		*LEG SHIELD	Broken	78.00 FL	*78.00 FL	
11	1		*FRONT PANEL	Broken	135.00 FL	*135.00 FL	
12	1		*PANEL EMBLEM LOGO	Necessary	98.00 FL	*98.00 FL	
13	2		*SIGNAL L/RH	Broken	150.00 FL	*150.00 FL	
14	1		*FRONT MUDGUARD	Broken	250.00 FL	*250.00 FL	
15	1		*SET FORK TUBE	Bent	480.00 FL	*480.00 FL	
16	1		*FORK UNDER BRACKET	Damaged	105.00 FL	*105.00 FL	
17	1		*RADIATOR ASSY	Not Necessary	380.00 FL	*-FL	
18	1		*FRONT RIM	Distorted	325.00 FL	*325.00 FL	
19	1		*FRONT BRAKE DISC	Not Necessary	280.00 FL	*-FL	
20	2		*FRONT SIDE PANEL L/RH	Dislodged / Broken	250.00 FL	*250.00 FL	
21	1		*REAR LH TAIL PANEL	Not Necessary	125.00 FL	*-FL	
22	1		*BALANCER	N/S Dislodged/O/SNot Necessary	160.00 FL	*80.00 FL	
23	1		*FRONT NUMBER PLATE	Missing	15.00 FS	*15.00 FS	
24	1		*REAR BOX	Not Necessary	450.00 FS	*-FS	
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	,	3,214.50	
			- List Item Disc	count on L Items 10.00/10.00% (S\$)	425.20	319.95	

Report was unsubmitted during this print-out.

Total Parts (S\$)

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING FEE	New	40.00	0.00
2	REMOVE & REPLACE NECESSARY PARTS ,ALIGN & ETC	New	250.00	180.00
3	REMOVE & REPLACE FORK ASSY ,FORK OIL SEAL ,TOP UP FORK OIL	New	180.00	80.00
4	SUPPLY BODY DECAL STICKER	New	120.00	80.00
5	RE-ALIGN /ADJUST FRONT BODY	New	250.00	120.00
6	REMOVE & REPLACE RIM ,BRAKE DISC	New	80.00	30.00
	Gross Labour Cost (S\$)		920.00	490.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >