

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012589/BGS3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800149993

Claimant
Vehicle No : SGZ7074X **Insured Vehicle No :** SMG3913E

Date of Loss: 15/11/2020 Nature of Claim: TP Claim No: 1529436063SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ7074X		
Make & Model:	DAIHATSU TERIOS, 1.5 (A)	Engine No:	1976249
Reg. Date:	14/11/2007 (Man. Year: 2007)	Chassis No:	JDAJ210G001058594
Colour:	Grey	Odometer:	176705 km
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,592.79	5,509.41	7,083.38	56.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	2,170.00	1,980.00	47.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,742.79	7,679.41	9,063.38	54.13
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	16,742.79	6,100.00	10,642.79	63.57
+ GST 7.00/7.00% (S\$)	1,172.00	427.00	745.00	63.57
Nett Amount (S\$)	17,914.79	6,527.00	11,387.79	63.57
+ Car Rental (9.0 x S\$110.00/day) (S\$)		990.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		7,553.45		

INSPECTION

Date of Assignment: 16/11/2020

Date Inspected: 17/11/2020 Inspected At:

160 SIN MING DRIVE #01-04
Repairer: Team Autopro Pte Ltd (KAKI BUKIT)

Estimated Period of Repair: 8.0 days

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	695.85 FL	*655.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	179.40 FL	*97.20 FL
3	2		*REAR BUMPER REFLECTOR	Broken	157.80 FL	*132.50 FL
4	2		*REAR BUMPER SUPPORT BRACKET	No such part	274.80 FL	*- FL
5	1		*REAR NUMBER PLATE LAMP	Not Damaged	128.50 FL	*- FL
6	1		*REAR BUMPER TOW COVER	Not Damaged	48.69 FL	*- FL
7	1		*TAILGATE	Dented	1,340.30 FL	*781.50 FL
8	1		*TAILGATE LOGO	No such part	84.60 FL	*- FL
9	1		*TAILGATE EMBLEM DAIHATSU	Necessary	58.00 FL	*58.00 FL
10	1		*TAILGATE EMBLEM TERIOS	Necessary	88.00 FL	*76.70 FL
11	1		*TAILGATE INNER TRIM BOARD	Broken	452.30 FL	*215.00 FL
12	1		*TAILGATE WEATHERSTRIP	Torn	186.60 FL	*186.60 FL
13	1		*TAILGATE INNER LOCK	Jammed	287.90 FL	*287.90 FL
14	1		*TAILGATE INNER LOCK STICKER	Not Damaged	62.30 FL	*- FL
15	1		*TAILGATE WINDSCREEN MOULDING	Necessary	287.00 FL	*128.30 FL
16	1		*SPARE TYRE COVER INNER	Broken	1,458.00 FL	*339.30 FL
17	1		*SPARE TYRE COVER OUTER	Broken	1,275.00 FL	*1,275.00 FL
18	1		*SPARE TYRE COVER OUTER LOGO	Necessary	84.60 FL	*84.60 FL
19	1		*SPARE TYRE BRACKET	Dented	358.10 FL	*358.10 FL
20	1		*REAR END PANEL	Dented	868.00 FL	*480.20 FL
21	1		*REAR END PANEL TOP GARNISH	Not Damaged	210.00 FL	*- FL
22	1		*REAR FLOOR PANEL TOP BOARD	Not Damaged	580.00 FL	*- FL
23	1		*REAR FENDER LH	Repair	885.30 FL	*- FL
24	1		*REAR FENDER INNER COWLING LH	Torn	84.00 FL	*84.00 FL
25	2		*REAR FENDER INNER TRIM BOARD	Not Damaged	1,374.40 FL	*- FL
26	1		*REAR FENDER SIDE GLASS MOULDING	Not Damaged	110.00 FL	*- FL
27	2		*TAILLAMP	Broken	866.20 FL	*630.00 FL
28	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
29	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
30	1		*TAILGATE SEALANT	Necessary	100.00 FS	*50.00 FS
31	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
32	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
33	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
34	1		*TAILGATE WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
35	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
36	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
38	1		*REAR FENDER SIDE GLASS SEALANT	Not Necessary	100.00 FS	*- FS
39	1		*REAR FENDER SIDE GLASS INNER SEAL	Not Necessary	80.00 FS	*- FS
40	1		*REAR FENDER SIDE GLASS PRIMER & CLEANER	Not Necessary	60.00 FS	*- FS
41	1		*REAR FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*30.00 FS
42	1		*REAR FENDER INNER TRIM BOARD CLIPS	N/S Necessary	100.00 FS	*30.00 FS
43	2		*TAILLAMP CLIPS	Necessary	100.00 FS	*30.00 FS
44	2		*TAILLAMP SEAL	No such part	120.00 FS	*- FS
45	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS
46	1		*REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **14,465.64** **6,389.90**
- List Item Discount on L Items 15.00/15.00% (\$\$) **1,872.85** **880.49**

Total Parts (\$\$) **12,592.79** **5,509.41**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REVERSE SENSOR	New	100.00	60.00
4	R&R REAR FENDER SIDE GLASS	New	250.00	0.00
5	CHECK WIRING	New	100.00	50.00
6	UPHOLSTERY	New	300.00	0.00
7	PANEL BEAT	New	1,400.00	800.00
8	RUST PROOFING	New	200.00	60.00
9	SPRAY PAINTING	New	1,400.00	1,000.00
Gross Labour Cost (\$)			4,150.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >