

TPChina.

Shirley, Alan, Adrian JSAEZC21S00176600

SGV5325G Suzuki

| | Date | No. |
|---|--------------------------------|-------------|
| Rear RH Fender Distorted | 387.40 | ✓ |
| " " " Inner shield ^{torn} | 80.65 | ✓ |
| " " " Inner shield clip - 84 x 12 ^{new} | 48.00 | 30 |
| Rear RH Door - Repair | 690.95 | X |
| " " " Lock ^{2 NP} | 177.45 | X |
| " " " Rubber ^{door} | 87.45 | X |
| " " " Door Hinge ^{2 x 0} x 46.35 ^{NP} | 92.70 | X |
| Tail Lamp RH Smashed | 248.65 | ✓ |
| " " Panel RH Dented | 80.65 | ✓ |
| Rear Bumper Distorted | 607.20 | 456 |
| " " RH side retainer ^{new} | 18.70 | ✓ |
| Rear Mud flap (Per set) ^{NP} | 205.60 | X |
| Rear RH Hub (Drum) ^{3 Dmg} | 216.25 | ✓ |
| " " Bearing Hub | 80.65 | ✓ |
| Rear Cross Member Bent | 1240.00 | 732 |
| Rear RH Shock Absorber Bent | 195.25 | ✓ |
| Rear RH Spond Rim lit | 468.25 | ✓ |
| Rear RH Tyre ^{x 1 NP} | 280.00 | X |
| Rear End Panel Dented | 303.60 | ✓ |
| | 5509.90 | |
| 329805 | Loss 15% | 826.48 |
| Less 15% 280334 | | 4683.43 |
| | | |
| | Spray painting | 950.00 800 |
| | Panel beating to replace parts | 1500.00 900 |
| 2060 | To repair under carriage | 350.00 250 |
| | To adjust lambar | 150.00 80 |
| | To check wiring | 120.00 30 |
| | | 7753.44 |
| total: 4305.28 | | |
| As: 30K | Lump Sum: #6202 | |
| 0.5 Days | (3.9K) | |