

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG16017980/UPA3Q2-1

**Date:** 10/12/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	999995580
<b>Claimant</b>		
<b>Vehicle No :</b> YL4190Z	<b>Insured Vehicle No :</b>	SKG4544D
Date of Loss: 01/09/2016	Nature of Claim: TP	Claim No: 1030817422SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>YL4190Z</b>		
Make & Model:	MITSUBISHI FE639C6SRDEA, 3.9 D (M)	Engine No:	4D34J43878
Reg. Date:	07/06/2003 (Man. Year: 2003)	Chassis No:	FE639CA40558
Colour:	White	Odometer:	355793 km
Engine Capacity:	3908 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	7.00-16	Rear Tyre Size:	7.00-16 (D)
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6/6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,613.30	2,281.46	2,331.84	50.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	720.00	430.00	37.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,763.30</b>	<b>3,001.46</b>	<b>2,761.84</b>	<b>47.92</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,763.30</b>	<b>2,400.00</b>	<b>3,363.30</b>	<b>58.36</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
		<b>(S\$)</b>	2,900.00	
<b>Liabe Amount (50.00%) (S\$)</b>		<b>1,450.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		5.35		
<b>Nett Liability (S\$)</b>		<b>1,455.35</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,450.00</b>		

### INSPECTION

Date of Assignment:	23/09/2016	
Date Inspected:	23/09/2016 Inspected At:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH CORNER PANEL	Dented	1,066.00 F	*502.14 FL
2	1		*FRONT LH SIDE LAMP	Cracked	162.00 F	*162.00 FL
3	1		*FRONT LH SIGNAL LAMP	Grazed	241.00 F	*241.00 FL
4	1		*FRONT LH GRILLE	Grazed	1,066.00 F	*745.11 FL
5	1		*FRONT LH STEP GARNISH	Distorted	148.50 F	*148.50 FL
6	1		*FRONT LH BUMPER	Distorted	1,929.80 F	*1,243.20 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,613.30</b>	<b>3,041.95</b>
<b>- List Item Discount on L Items 0.00/25.00% (S\$)</b>	0.00	760.49
<b>Total Parts (S\$)</b>	<b>4,613.30</b>	<b>2,281.46</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	600.00	300.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	500.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,150.00</b>	<b>720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >