

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20012598/AVF3E2

Date: 04/08/2021

REFERENCE

Insured/Claimant:	PHNG HWEE LENG MERVIN	Policy No:	2100385096	
Date of Loss:	11/11/2020	Nature of Claim:	OD	Claim No: 0467553777SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG3998J	Engine No:	CEP010983
Make & Model:	AUDI RS3, 2.5 Sportback (A)	Chassis No:	WUAZZZ8P5D1900009
Reg. Date:	29/08/2012 (Man. Year: 2012)	Odometer:	49936 km
Colour:	Grey		
Engine Capacity:	2480 cc		
Market Value/New Car Price:	S\$73,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	66,774.00	30,640.64	36,133.36	54.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	30,484.00	16,294.00	14,190.00	46.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	97,258.00	46,934.64	50,323.36	51.74
Approved Total (Overridden) (S\$)		34,000.00		
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	94,258.00	31,000.00	63,258.00	67.11
+ GST 7.00/7.00% (S\$)	6,598.06	2,170.00	4,428.06	67.11
Nett Amount (S\$)	100,856.06	33,170.00	67,686.06	67.11

INSPECTION

Date of Assignment: 16/11/2020

Date Inspected: 16/11/2020 Inspected At:

24 BENOI SECTOR

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	5,789.00 FS	*4,631.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	258.00 FS	*- FS
3	1		*FRONT BUMPER CARRIER	Not Necessary	1,145.00 FS	*- FS
4	1		*FRONT BUMPER SHOCK ABSORBER - LH	Not Necessary	342.00 FS	*- FS
5	1		*FRONT BUMPER GUIDE SECTION - LH / RH	N/S Damaged	624.00 FS	*249.20 FS
6	1		*RADIATOR GRILLE	Cracked	4,201.00 FS	*3,360.80 FS
7	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	647.00 FS	*- FS
8	1		*RS3 INSCRIPTION	Necessary	122.00 FS	*97.60 FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	832.00 FS	*- FS
10	1		*FRONT BUMPER END CAP	Not Necessary	268.00 FS	*- FS
11	2		*FRONT BUMPER TRIM STRIPS - LH / RH	Not Necessary	850.00 FS	*- FS
12	1		*FRONT BUMPER SPOILER - LOWER CENTRE	Not Necessary	1,411.00 FS	*- FS
13	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	397.00 FS	*- FS
14	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	268.00 FS	*- FS
15	1		*SPRING SHACKLE	Not Necessary	66.00 FS	*- FS
16	2		*SIGNAL HORN - LOW / HIGH TONE	Not Necessary	446.00 FS	*- FS
17	2		*FRONT FENDER - LH / RH	Distorted	12,602.00 FS	*10,081.60 FS
18	1		*FRONT FENDER BRACE - LH FRONT	Bent	53.00 FS	*42.24 FS
19	2		*FRONT FENDER BRACKET - LH / RH LOWER	Damaged	162.00 FS	*128.80 FS
20	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Cracked	184.00 FS	*147.04 FS
21	2		*WHEEL HOUSING LINER - LH / RH INNER	Torn	586.00 FS	*468.00 FS
22	2		*WHEEL HOUSING LINER - LH / RH OUTER	Torn	586.00 FS	*468.00 FS
23	1		*WHEEL SPOILER - LH / RH	N/S Torn	134.00 FS	*53.44 FS
24	2		*WHEEL HOUSING SOUND ABSORBER - LH / RH	Not Necessary	212.00 FS	*- FS
25	1		*BONNET	Not Necessary	2,373.00 FS	*- FS
26	2		*BONNET LID HINGE - LH / RH	Not Necessary	114.00 FS	*- FS
27	1		*BONNET CATCH HOOK	Not Necessary	92.00 FS	*- FS
28	1		*BONNET LID LOCK	Not Necessary	212.00 FS	*- FS
29	1		*BONNET LOCK COVER - UPPER FRONT	Not Necessary	51.00 FS	*- FS
30	1		*HEADLIGHT - LH / RH	N/S Cracked	4,556.00 FS	*1,822.40 FS
31	1		*GAS DISCHARGE LAMP	Not Necessary	408.00 FS	*- FS
32	1		*GAS DISCHARGE LAMP CONTROL UNIT	Not Necessary	1,084.00 FS	*- FS
33	1		*CORNERING LIGHT POWER MODULE	Not Necessary	1,043.00 FS	*- FS
34	1		*HEADLIGHT HOSE - LH	Not Necessary	12.00 FS	*- FS
35	1		*FLAT CONTACT HOUSING	Cracked	30.00 FS	*23.60 FS
36	1		*LIFT CYLINDER - LH	Cracked	201.00 FS	*160.80 FS
37	5		*LIFT CYLINDER HOSE	Not Necessary	184.00 FS	*- FS
38	1		*WASH WATER RESERVOIR	Not Necessary	170.00 FS	*- FS
39	1		*LOCK CARRIER	Not Necessary	2,289.00 FS	*- FS
40	1		*AIRCON CONDENSER	Not Necessary	1,079.00 FS	*- FS
41	1		*AIRCON STICKER	Necessary	18.00 FS	*13.84 FS
42	1		*ADDITIONAL RADIATOR	Not Necessary	1,874.00 FS	*- FS
43	2		*ADDITIONAL RADIATOR BRACKET - LH / RH	Not Necessary	426.00 FS	*- FS
44	1		*READY MIX COOLANT	Not Necessary	91.00 FS	*- FS
45	1		*RADIATOR AIR GUIDE - LH	Not Necessary	39.00 FS	*- FS
46	1		*RADIATOR AIR GUIDE - LH OUTER	Not Necessary	78.00 FS	*- FS
47	1		*FRONT DOOR - RH	Distorted	2,176.00 FS	*1,740.80 FS
48	1		*FRONT DOOR HINGE - RH LOWER	Bent	237.00 FS	*189.60 FS
49	1		*FRONT DOOR HINGE - RH UPPER	Not Necessary	71.00 FS	*- FS
50	1		*DOOR HINGE RETAINING PLATE	Not Necessary	13.00 FS	*- FS
51	1		*FRONT DOOR SIDE REINFORCEMENT	Not Necessary	157.00 FS	*- FS
52	1		*FRONT DOOR INNER SEAL	Not Necessary	250.00 FS	*- FS
53	1		*TYRE PRESSURE DATA PLATE	Necessary	20.00 FS	*15.36 FS
54	1		*EXTERIOR MIRROR MOUNTING - RH	Not Necessary	1,013.00 FS	*- FS
55	1		*MIRROR CAP - RH	Cut	1,282.00 FS	*1,025.60 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*MIRROR GLASS - RH	Not Necessary	1,644.00 FS	*- FS
57	1		*TURN SIGNAL INDICATOR	Not Necessary	99.00 FS	*- FS
58	1		*FRONT DOOR COVER - RH	Distorted	326.00 FS	*260.80 FS
59	1		*FRONT DOOR PROTECTIVE STRIP - RH	Deformed	201.00 FS	*160.80 FS
60	1		*SIDE MEMBER TRIM - RH	Distorted	1,029.00 FS	*823.20 FS
61	1		*SIDE MEMBER TRIM CAP - RH	Missing	164.00 FS	*131.20 FS
62	1		*A-PILLAR - RH	Distorted	1,120.00 FS	*896.00 FS
63	1		*SILL TRIM STRIP - RH OUTER	Not Necessary	679.00 FS	*- FS
64	1		*SILL TRIM STRIP - RH INNER	Not Necessary	187.00 FS	*- FS
65	1		*DATA TAG	Not Necessary	457.00 FS	*- FS
66	1		*NOISE INSULATION	Not Necessary	746.00 FS	*- FS
67	1		*UNDERBODY TRIM	Not Necessary	245.00 FS	*- FS
68	2		*FRONT ALUMINIUM RIM - LH / RH	Cut	2,728.00 FS	*2,182.40 FS
69	1		*TRACJ CONTROL ARM - LH	Not Necessary	371.00 FS	*- FS
70	1		*WHEEL BEARING HOUSING - LH	Not Necessary	666.00 FS	*- FS
71	1		*WHEEL BEARING	Damaged	949.00 FS	*759.20 FS
72	1		*GUIDE JOINT - LH	Bent	136.00 FS	*108.40 FS
73	1		*TIE ROD END - LH	Not Necessary	122.00 FS	*- FS
74	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
75	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
76	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
77	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
78	1		*SUNDRIES	Necessary	400.00 FS	*445.12 FS
79	1		*HEADLIGHT MOUNTING-LH (Supplementary)	Cracked	117.00 FS	*93.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	66,774.00	30,640.64
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER	New	800.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	0.00
4	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY	New	1,800.00	1,800.00
5	TO REMOVE AND REINSTALL CENTRE CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES	New	3,200.00	3,200.00
6	TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	1,800.00
7	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	280.00
8	TO PLACE VEHICLE ON CAR O-LINER	New	2,400.00	0.00
9	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS, RHS FRONT DOOR AND RHS SILL PANEL TRIM. CUT OUT AND REWELD RHS LOWER A-PILLAR AND RHS SILL PANEL. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	9,800.00	4,000.00
10	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, RHS LOWER A-PILLAR, RHS SILL PANEL, RHS SILL PANEL TRIM, DOOR ENTRANCE, RHS FRONT DOOR, RHS WING MIRROR COVER AND DOOR COVER. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT	New	7,900.00	4,150.00
11	TO RENEW BOTH FRONT RIMS. TO CARRY OUT PRE AND POST REPAIR WHEEL ALIGNMENT CHECK	New	560.00	320.00
12	TO CARRY OUT PRE AND POST REPAIR DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			30,484.00	16,294.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >