

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012599/ABS3Q2
Date: 10/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800071456
Claimant Vehicle No :	SLK5947K	Insured Vehicle No :	SME9X
Date of Loss:	15/11/2020	Nature of Claim:	TP
		Claim No:	4672174798SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK5947K	Engine No:	L13A4098947
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61088829
Reg. Date:	30/09/2008 (Man. Year: 2008)	Odometer:	203446 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,769.80	5,677.12	3,092.68	35.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	2,550.00	850.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,169.80	8,227.12	3,942.68	32.40
Approved Total (Overridden) (S\$)		6,500.00		

Nett Amount (S\$)	12,169.80	6,500.00	5,669.80	46.59
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,507.45		
Global Sum Settlement (S\$)		7,500.00		

INSPECTION

Date of Assignment: 16/11/2020

Date Inspected: 17/11/2020

Estimated Period of Repair: 9.0 days

Inspected At:

Sin Yu Sin Workshop (HQ)
1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit)
Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	967.60 FL	*845.00 FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	120.40 FL	*120.40 FL
3	1		*REAR TAILGATE LOGO EMBLEM	Necessary	35.00 FL	*35.00 FL
4	1		*REAR TAILGATE FIT EMBLEM	Necessary	38.00 FL	*38.00 FL
5	2		*REAR TAILGATE NO PLATE LAMP L/R	Not Necessary	65.60 FL	*- FL
6	1		*REAR TAILGATE NO PLATE LAMP GARNISH	Cracked	185.20 FL	*185.20 FL
7	1		*REAR TAILGATE WEATHERSTRIP	Cut	142.30 FL	*142.30 FL
8	2		*REAR TAILGATE DAMPER L/R	Not Necessary	272.60 FL	*- FL
9	1		*REAR TAILGATE MECHANISM LOCK	Damaged	263.90 FL	*189.00 FL
10	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	55.00 FL	*- FL
11	1		*REAR TAILGATE INNER TRIM	Cracked	296.30 FL	*296.30 FL
12	12		*REAR TAILGATE INNER TRIM CLIP	Necessary	54.00 FL	*30.00 FL
13	1		*REAR TAILLAMP RH	Cracked	348.20 FL	*288.00 FL
14	1		*REAR TAILLAMP BRACKET RH	Not Necessary	55.00 FL	*- FL
15	1		*REAR TAILLAMP PANEL RH	Dented	230.80 FL	*230.80 FL
16	1		*REAR BUMPER	Distorted	660.90 FL	*495.00 FL
17	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	91.80 FL	*91.80 FL
18	1		*REAR BUMPER TOWING COVER	Distorted	59.20 FL	*59.20 FL
19	1		*REAR END PANEL	Dented	386.50 FL	*386.50 FL
20	1		*REAR END PANEL GARNISH	Deformed	140.80 FL	*140.80 FL
21	1		*REAR SPARE TYRE PANEL	Distorted	737.00 FL	*737.00 FL
22	1		*REAR SPARE TYRE PANEL TOP SPONGE	Deformed	243.80 FL	*243.80 FL
23	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	282.80 FL	*282.80 FL
24	1		*REAR EXHAUST HEAT SHIELD	Crumpled	168.90 FL	*168.90 FL
25	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	41.60 FL	*- FL
26	1		*REAR SUB CHASSIS RH	Repair	380.50 FL	*- FL
27	1		*REAR SUB CHASSIS TOP PANEL RH	Repair	157.80 FL	*- FL
28	1		*REAR FENDER RH	Repair	820.60 FL	*- FL
29	1		*REAR FENDER AIR VENT RH	Not Necessary	76.80 FL	*- FL
30	1		*REAR FENDER INNER TRIM RH	Cracked	335.60 FL	*335.60 FL
31	12		*REAR FENDER INNER TRIM CLIP RH	Necessary	54.00 FL	*30.00 FL
32	1		*REAR NUMBER PLATE	Not Necessary	25.00 FS	*- FS
33	1		*REAR NUMBER PLATE GARNISH	Not Necessary	50.00 FS	*- FS
34	1		*REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
35	1		*REAR REVERSE CAMERA	Not Necessary	400.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
37	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
38	1		*REAR SPARE TYRE PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
39	1		*REAR EXHAUST SILENCER (HKS)	Bent	1,500.00 FS	*1,000.00 FS
40	1		*REAR FENDER WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
41	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,323.50	6,751.40
- List Item Discount on L Items 20.00/20.00% (S\$)	1,553.70	1,074.28
Total Parts (S\$)	8,769.80	5,677.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRINGS	New	80.00	30.00
2	TO TRANSFER TAILGATE COMPONENT PARTS TO NEW BOOT	New	100.00	80.00
3	TO REMOVE AND REINSTALL REAR WINDSCREEN FOR NECESSARY REPAIR	New	150.00	120.00
4	TO REMOVE AND REINSTALL REAR FENDER GLASS FOR NECESSARY REPAIR	New	120.00	0.00
5	TO REMOVE ,REPLACE AND REINSTALL REAR REVERSE SENSOR	New	80.00	50.00
6	TO REMOVE,REPLACE AND REINSTALL REAR REVERSE CAMERA	New	80.00	50.00
7	TO REMOVE ,AND REINSTALL EXHAUST SILENCER FOR NECESSARY	New	120.00	80.00
8	TO REMOVE ,REINSTALL CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET	New	120.00	60.00
9	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	New	150.00	80.00
10	TO STRAIGHTEN ,REPAIR ,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,200.00	1,000.00
11	TO SPRAY PAINTING ON AFFECTED AREA	New	1,200.00	1,000.00
Gross Labour Cost (S\$)			3,400.00	2,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >