

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20012610/ARA3Q2

Date: 10/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900232699

Claimant
Vehicle No : SLB7219M **Insured Vehicle No :** SMP9577E

Date of Loss: 13/11/2020 Nature of Claim: TP Claim No: 5078544519SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB7219M		
Make & Model:	MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A)	Engine No:	4A92CD9665
Reg. Date:	20/04/2016 (Man. Year: 2015)	Chassis No:	JMYSRCY1AGU003391
Colour:	Silver	Odometer:	91829 km
Engine Capacity:	1590 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	25/60R16	Rear Tyre Size:	25/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,813.00	4,101.00	1,712.00	29.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,870.00	1,080.00	36.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,763.00	5,971.00	2,792.00	31.86
Approved Total (Overridden) (S\$)		4,750.00		
(S\$)	8,763.00	4,750.00	4,013.00	45.79
+ GST 7.00/7.00% (S\$)	613.41	332.50	280.91	45.79
Nett Amount (S\$)	9,376.41	5,082.50	4,293.91	45.79
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,684.50		
Global Sum Settlement (S\$)		5,600.00		

INSPECTION

Date of Assignment: 19/11/2020

Date Inspected: 19/11/2020 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP -LH & RH	Not Necessary	64.00 FL	*- FL
2	1		*REAR BUMPER	Distorted	855.00 FL	*855.00 FL
3	2		*REAR BUMPER SIDE HOLDER -RH & LH	Necessary	70.00 FL	*70.00 FL
4	1		*REAR BUMPER BEAM	Bent	169.00 FL	*169.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	254.00 FL	*254.00 FL
6	1		*REAR BUMPER REFLECTOR -LH & RH	N/S Cracked	76.00 FL	*38.00 FL
7	1		*REAR BUMPER TOW COVER	Not Necessary	27.00 FL	*- FL
8	1		*REAR END PANEL	Dented	506.00 FL	*506.00 FL
9	1		*REAR END PANEL TOP GARNISH	Cracked	145.00 FL	*145.00 FL
10	1		*REAR END PANEL SMART ENTRY ANTENNA	Damaged	142.00 FL	*142.00 FL
11	2		*TAIL LAMP -LH & RH	Not Necessary	808.00 FL	*- FL
12	2		*TAIL LAMP PANEL-LH & RH	Not Necessary	358.00 FL	*- FL
13	1		*BOOTLID	Buckled	755.00 FL	*755.00 FL
14	1		*BOOTLID LOCK	Damaged	155.00 FL	*155.00 FL
15	1		*BOOTLID WEATHERSTRIPE	Cut	161.00 FL	*161.00 FL
16	2		*BOOTLID HINGE	Not Necessary	190.00 FL	*- FL
17	1		*MITSUBISHI LOGO	Necessary	58.00 FL	*58.00 FL
18	1		*LANCER EMBLEM	Necessary	55.00 FL	*55.00 FL
19	1		*MIVEC EMBLEM	Necessary	48.00 FL	*48.00 FL
20	1		*CYCLE AND CARRIAGE LOGO	Necessary	56.00 FL	*56.00 FL
21	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	195.00 FL	*- FL
22	1		*REAR FENDER INNER TRIM -LH	Torn	223.00 FL	*223.00 FL
23	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
24	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
25	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
26	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
27	1		*REAR CAMERA	Damaged	480.00 FS	*380.00 FS
28	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
29	1		*SET REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
30	1		*SET REAR FENDER INNER TRIM CLIPS -LH	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,350.00	4,470.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	537.00	369.00
Total Parts (\$\$)	5,813.00	4,101.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	800.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	800.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	80.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
Gross Labour Cost (\$\$)			2,950.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >