

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012618/ABA3Q2
Date: 10/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100376645
Claimant Vehicle No :	SMK5278X	Insured Vehicle No :	SKN4679L
Date of Loss:	13/11/2020	Nature of Claim:	TP
		Claim No:	0752580236SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK5278X	Engine No:	L13B1455859
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Chassis No:	GK31346947
Reg. Date:	12/04/2019 (Man. Year: 2019)	Odometer:	29394 km
Colour:	Red		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,859.52	24,205.52	18,654.00	43.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,600.00	4,540.00	7,060.00	60.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	54,459.52	28,745.52	25,714.00	47.22
Approved Total (Overridden) (S\$)		23,000.00		

Nett Amount (S\$)	54,459.52	23,000.00	31,459.52	57.77
+ Car Rental (19.0 x S\$100.00/day) (S\$)		1,900.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		24,996.45		
Global Sum Settlement (S\$)		24,900.00		

INSPECTION

Date of Assignment: 16/11/2020

Date Inspected: 18/11/2020

Inspected At:

Ishare Auto Pte. Ltd. (HQ)
 8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT
 Singapore 415875

Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	517.70 FL	*517.70 FL
2	1		*FRONT BUMPER LOWER LIP	Not Necessary	126.30 FL	*- FL
3	1		*FRONT BUMPER FOGLAMP COVER GARNISH RH	Missing	39.20 FL	*39.20 FL
4	1		*FRONT BUMPER LOWER GRILLE	Deformed	180.40 FL	*180.40 FL
5	1		*FRONT BUMPER LOWER GRILLE SIDE GARNISH	O/S Cracked	37.00 FL	*18.50 FL
6	1		*FRONT BUMPER TOW COVER	Not Necessary	21.40 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	313.80 FL	*313.80 FL
8	1		*FRONT BUMPER SIDE RETAINER	O/S Damaged	30.80 FL	*15.40 FL
9	1		*ENGINE UNDER COVER GARNISH	Cracked	84.30 FL	*84.30 FL
10	1		*ENGINE SIDE COVER GARNISH RH	Deformed	69.20 FL	*69.20 FL
11	1		*HEADLAMP	O/S Smashed	1,590.40 FL	*795.20 FL
12	1		*HEADLAMP LOWER BRACKET	O/S Smashed	70.40 FL	*35.20 FL
13	1		*HEADLAMP WIRE HARNESS RH	Not Necessary	326.10 FL	*- FL
14	1		*CENTER GRILLE	Cracked	227.40 FL	*227.40 FL
15	1		*CENTER GRILLE LOGO	Necessary	28.40 FL	*28.40 FL
16	1		*CENTER GRILLE UPPER CHROME	Not Necessary	224.80 FL	*- FL
17	1		*CENTER GRILLE LOWER CHROME	Not Necessary	202.40 FL	*- FL
18	1		*CENTER GRILLE BRACKET	Not Necessary	32.80 FL	*- FL
19	1		*CENTER GRILLE INNER GARNISH	Not Necessary	22.40 FL	*- FL
20	1		*BONNET	Not Necessary	550.90 FL	*- FL
21	1		*BONNET LOCK	Not Necessary	87.70 FL	*- FL
22	2		*BONNET STOPPER	Not Necessary	37.80 FL	*- FL
23	2		*BONNET HINGE	Not Necessary	81.00 FL	*- FL
24	2		*BONNET INNER RUBBER	Not Necessary	118.40 FL	*- FL
25	1		*FRONT SUPPORT PANEL	Distorted	555.20 FL	*555.20 FL
26	1		*FRONT SUPPORT LOWER APRON PANEL	Distorted	97.20 FL	*97.20 FL
27	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed	110.30 FL	*110.30 FL
28	1		*AIR DUCT	Not Necessary	59.20 FL	*- FL
29	1		*WIPER TANK	Deformed	75.20 FL	*75.20 FL
30	1		*WIPER TANK TUBE	Not Necessary	25.40 FL	*- FL
31	1		*WIPER WASHER TANK MOTOR	Not Necessary	59.40 FL	*- FL
32	1		*AIR CON CONDENSER	Not Necessary	810.20 FL	*- FL
33	4		*AIR CON CONDENSER MOUNTING RUBBER	Not Necessary	156.80 FL	*- FL
34	2		*AIR CON CONDENSER BRACKET	Not Necessary	70.80 FL	*- FL
35	2		*AIR CON CONDENSER SIDE GARNISH	Not Necessary	65.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*RADIATOR	Cracked	1,250.40 FL	*1,250.40 FL
37	2		*RADIATOR RUBBER MOUNTING	Not Necessary	78.40 FL	*- FL
38	1		*RADIATOR TOP HOSE	Not Necessary	45.20 FL	*- FL
39	1		*RADIATOR FAN MOTOR	Not Necessary	319.20 FL	*- FL
40	1		*RADIATOR FAN COWLING	Not Necessary	125.90 FL	*- FL
41	1		*RADIATOR FAN BLADE	Not Necessary	78.20 FL	*- FL
42	1		*RADIATOR SPARE TANK	Not Necessary	50.10 FL	*- FL
43	2		*HORN	Not Necessary	138.40 FL	*- FL
44	1		*SET ENGINE MOUNTING	Not Necessary	799.20 FL	*- FL
45	1		*SET ENGINE MOUNTING HOUSING RH	Not Necessary	174.10 FL	*- FL
46	1		*AUTO GEAR BOX	Damaged	11,900.80 FS	*5,500.00 FS
47	1		*FRONT FENDER RH	Distorted	435.20 FL	*435.20 FL
48	1		*FRONT FENDER INNER GARNISH RH	Deformed	51.50 FL	*51.50 FL
49	1		*FRONT FENDER INNER SHIELD RH	Deformed	81.50 FL	*81.50 FL
50	1		*FRONT FENDER QUARTER GLASS C/W MOULDING RH	Necessary	55.20 FL	*55.20 FL
51	1		*FRONT WHEEL HOUSE RH	Repair	295.40 FL	*- FL
52	1		*FRONT WHEEL HOUSE SUPPORTPANEL RH	Bent	129.00 FL	*129.00 FL
53	1		*FRONT WHEEL HOUSE EXTEND PANEL RH	Bent	139.00 FL	*139.00 FL
54	1		*FRONT CHASSIS SIDE SUPPORT PANEL (INNER)	Repair	58.00 FL	*- FL
55	1		*FRONT CHASSIS SIDE SUPPORT PANEL (OUTER)	Repair	65.00 FL	*- FL
56	1		*FRONT WINDSCREEN MOULDING	Not Necessary	169.20 FL	*- FL
57	1		*FRONT WINDSCREEN SIDE MOULFING RH	Not Necessary	102.30 FL	*- FL
58	1		*FRONT WHEEL RIM RH	Bent	668.96 FS	*200.00 FS
59	1		*FRONT WHEEL CAP RH	Cracked	213.60 FL	*213.60 FL
60	1		*FRONT CROSS MEMBER	Bent	1,250.40 FL	*1,250.40 FL
61	1		*FRONT STEERING RACK AND PINION	Bent	1,650.20 FL	*1,650.20 FL
62	1		*FRONT DRIVESHAFT RH	Bent	976.20 FL	*976.20 FL
63	1		*FRONT DRIVESHAFT OIL SEAL RH	Necessary	19.20 FL	*19.20 FL
64	1		*FRONT KNUCKLE ARM RH	Damaged	230.40 FL	*230.40 FL
65	1		*FRONT LOWER ARM RH	Bent	160.20 FL	*160.20 FL
66	1		*FRONT SHOCK ABSORBER RH	Bent	310.20 FL	*310.20 FL
67	1		*FRONT ABS SENSOR RH	Not Necessary	299.40 FL	*- FL
68	1		*FRONT WHEEL HUP RH	Damaged	138.30 FL	*138.30 FL
69	1		*FRONT WHEEL HUP BEARING RH	Necessary	168.20 FL	*168.20 FL
70	1		*FRONT STABILIZER BAR	Bent	189.20 FL	*189.20 FL
71	1		*FRONT LINKAGE RH	Bent	49.80 FL	*49.80 FL
72	1		*FRONT ABS PUMP	Cracked	3,994.24 FS	*2,500.00 FS
73	1		*CENTER PILLAR INNER GARNISH	Not Necessary	324.90 FL	*- FL
74	1		*FRONT DOOR PILLAR (OUTER) RH	Not Necessary	899.40 FL	*- FL
75	1		*FRONT DOOR SIDE MIRROR RH	Cut	527.40 FL	*527.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*FRONT DOOR RH	Repair	1,050.20 FL	*- FL
77	1		*FRONT DOOR BLACK STICEKR	Not Necessary	39.20 FL	*- FL
78	2		*FRONT DOOR HINGE RH	Not Necessary	84.80 FL	*- FL
79	1		*FRONT DASHBOARD	Torn	718.20 FL	*718.20 FL
80	1		*FRONT SEAT RH	Bent	1,317.68 FS	*1,000.00 FS
81	2		*FRONT SAFETY BELT	Activated	928.40 FL	*928.40 FL
82	1		*FRONT PASSENGER AIR BAG	Activated	2,236.40 FL	*2,236.40 FL
83	1		*FRONT STEERING WHEEL AIR BAG	Activated	1,605.20 FL	*1,605.20 FL
84	2		*FRONT AIR BAG SENSOR	Activated	314.40 FL	*314.40 FL
85	1		*FRONT AIR BAG CONTROL UNIT	Activated	747.20 FL	*747.20 FL
86	1		*AIR FRONT BAG WIRE HARNESS	Activated	269.40 FL	*269.40 FL
87	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
88	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
89	1		*SET FRONT BUMPER LOWER GRILLE CLIP	Necessary	60.00 FS	*20.00 FS
90	1		*SET FRONT BUMPER LOWER GRILLE SIDE GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
91	1		*SET ENGINE UNDER COVER GARNISH CLIP	Necessary	80.00 FS	*30.00 FS
92	1		*SET ENGINE SIDE COVER GARNISH CLIP	Necessary	60.00 FS	*20.00 FS
93	1		*SET CENTER GRILLE CLIP	Necessary	60.00 FS	*20.00 FS
94	1		*SET CENTER GRILLE INNER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
95	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	150.00 FS	*- FS
96	1		*SET FRONT WIPER PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS
97	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
98	1		*FRONT WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
99	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	80.00 FS	*30.00 FS
100	1		*FRONT WHEEL HOUSE SEALANT RH	Not Necessary	150.00 FS	*- FS
101	1		*SET CENTER PILLAR INNER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
102	1		*FRONT DOOR PILLAR (OUTER) SEALANT RH	Not Necessary	150.00 FS	*- FS
103	1		*FRONT PILLAR QUARTER GLASS SEALANT LH	Necessary	80.00 FS	*30.00 FS
104	1		*FRONT PILLAR QUARTER GLASS INNER SEAL RH	Not Necessary	60.00 FS	*- FS
105	1		*FRONT PILLAR QUARTER GLASS SOLAR FILM RH	Not Necessary	250.00 FS	*- FS
106	1		*SET FRONT DASHBOARD CLIP	Necessary	120.00 FS	*50.00 FS
107	1		*FRONT WHEEL TYRE RH	Punctured	480.00 FS	*180.00 FS
108	1		*COOLANT	Necessary	80.00 FS	*50.00 FS
109	1		*SET DOOR VISOR	Not Necessary	350.00 FS	*- FS
110	1		*AUTO GEAR BOX OIL	Necessary	480.00 FS	*100.00 FS
111	1		*BRAKE OIL	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	48,288.98	27,806.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,429.46	3,601.38

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	42,859.52
						24,205.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	2,400.00	1,400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,250.00
3	TUFF COAT	New	250.00	80.00
4	WIRING BULB CHECKING	New	180.00	30.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
6	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIR CON GAS	New	120.00	60.00
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
8	REFOCUS HEADLAMP BEAM	New	60.00	0.00
9	REMOVE AND REFIX ENGINE MOUNTING	New	450.00	0.00
10	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
11	REMOVE AND REFIX FRONT SEAT	New	250.00	150.00
12	FRONT CHASSIS ALIGNMENT	New	250.00	0.00
13	REMOVE AND REFIX AUTO GEAE BOX	New	450.00	280.00
14	LIFT UP AND REFIX ENGINE	New	680.00	280.00
15	REMOVE AND REFIX FRONT CROSSMEMBER	New	350.00	150.00
16	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	220.00
17	REMOVE AND REPLACE STEERING RACK AND PINION	New	350.00	120.00
18	FOUR WHEEL ALIGNMENT	New	120.00	80.00
19	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	120.00	0.00
20	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	New	80.00	0.00
21	REMOVE AND REFIX FRONT DASHBOARD	New	850.00	220.00
22	REMOVE AND REFIX FRONT PILLAR QUARTER GLASS	New	80.00	40.00
23	RESET RADIO SYSTEM	New	200.00	0.00
24	REMOVE AND REFIX ABS PUMP	New	480.00	120.00
25	RESET ENGINE LIGHT	New	350.00	0.00
26	RESET ABS LIGHT	New	350.00	0.00
27	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			11,600.00	4,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >