

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20012626/T1TF3E2

**Date:** 23/11/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00010972000  
Claimant Vehicle No : SMC310K Insured Vehicle No : XE2082P  
Date of Loss: 11/11/2020 Nature of Claim: TP Claim No: SNM20D204388/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC310K**  
Make & Model: KIA FORTE K3, 1.6 EX (A) Engine No: G4FGJH697263  
Reg. Date: 26/06/2018 (Man. Year: 2017) Chassis No: KNAFJ411MJ5767267  
Colour: Dark Blue Odometer: 121443 km  
Engine Capacity: 1591 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,035.65	2,458.90	1,576.75	39.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,485.00	1,600.00	885.00	35.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>6,520.65</b>	<b>4,058.90</b>	<b>2,461.75</b>	<b>37.75</b>

### INSPECTION

Date of Assignment: 16/11/2020  
Date Inspected: 23/11/2020 Inspected At: Xinya Auto Services Pte Ltd (HQ)  
Blk 1002, #01-75, Bukit Merah Lane 3  
Singapore 159719  
Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2021)
<b>Parts:</b> 143	KIA FORTE K3 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMC310K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Repair	631.00 FL	*- FL	
2	2		*HEADLAMPS	Cut	1,620.00 FL	*1,620.00 FL	
3	1		*BONNET	Repair	1,224.00 FL	*- FL	
4	1		*WINDSCREEN GLASS	Chipped	1,093.00 FL	*1,093.00 FL	
5	1		*WINDSCREEN INNER SEAL	Necessary	61.00 FL	*61.00 FL	
6	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS	
7	1		*WINDSCREEN ERP STICKER	Necessary	5.00 FS	*5.00 FS	
8	6		*WINDSCREEN CLIPS	Necessary	21.00 FS	*21.00 FS	
9	1		*ERP BKT	Necessary	25.00 FS	*25.00 FS	
					<b>Sub Total (\$\$)</b>	<b>4,730.00</b>	<b>2,875.00</b>
					<b>- List Item Discount on L Items 15.00/15.00% (\$\$)</b>	694.35	416.10
					<b>Total Parts (\$\$)</b>	<b>4,035.65</b>	<b>2,458.90</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPLACE FRONT BUMPER, BONNET, FENDER RH, HEADLAMPS	New	1,000.00	400.00
2	TO PUTTY & SPRAY PAINT FRONT BUMPER, BONNET, FENDER RH, REAR RH DOOR, RH ROOF PANEL	New	1,200.00	1,000.00
3	TO REMOVE & REPLACE WINDSCREEN GLASS AND CHECK FOR WATER TIGHT	New	180.00	120.00
4	TO CHECK WIRING & FOCUS HEADLAMPS	New	45.00	30.00
5	PRIVATE HIRE REPLACE AT INSPECTION CENTRE	New	20.00	20.00
6	SEND VEHICLE FOR INSPECTION CHARGES	New	40.00	30.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,485.00</b>
				<b>1,600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >