



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 331U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (WCP)	BROKEN	940.00	940.00
1	FRONT BUMPER SPONGE (WCP)	SERVICEABLE	85.00	-
1	FRONT BUMPER INSIDE PART - RH (WCP)	CRACKED	45.00	45.00
1	FRONT BUMPER INSIDE PART - CENTRE (WCP)	SERVICEABLE	50.00	-
1	FRONT BUMPER CENTRE BRACKET (WCP)	CRACKED	65.00	65.00
1	FRONT BUMPER SIDE RETAINER (WCP)	NECESSARY	10.00	10.00
1	FRONT BUMPER PRESSURE SENSOR (WCP)	SERVICEABLE	100.00	-
2	FRONT BUMPER PRESSURE SENSOR RIVET @\$3.00 (WCP)	NOT NECESSARY	6.00	-
2	FRONT BUMPER PARKING SENSOR @\$95.00 (WCP)	MISSING (1PC ONLY)	190.00	95.00
6	FRONT BUMPER PARKING SENSOR SEAL @\$4.00 (WCP)	NECESSARY	24.00	24.00
1	FRONT BUMPER PARKING SENSOR WIRE HARNESS (WCP)	SERVICEABLE	130.00	-
1	FRONT BUMPER LOWER CENTRE GRILLE (WCP)	SERVICEABLE	55.00	-
1	FRONT BUMPER LOWER CHROME (WCP)	DISTORTED	105.00	105.00
1	RH FRONT BUMPER LOWER SIDE GRILLE (WCP) (WCP)	MISSING	20.00	20.00
1	RH FRONT BUMPER LOWER SIDE GRILLE COVER	MISSING	35.00	35.00
1	RH FRONT BUMPER LOWER SIDE GRILLE CHROME (WCP)	MISSING	55.00	55.00
1	FRONT BUMPER REINFORCEMENT (WCP)	TO REPAIR SEE LABOUR	260.00	-
10	FRONT BUMPER RIVET @\$3.00 (WCP)	NECESSARY	30.00	30.00
1	RH HEADLAMP ASSY (WCP)	CUT	1,650.00	1,650.00
1	RH FRONT FENDER INNER SHIELD - FRONT (WCP)	SERVICEABLE	110.00	-
8	RH FRONT FENDER INNER SHIELD CLIPS @\$4.00 (WCP)	NOT NECESSARY	32.00	-
	COST PLUS 151%		599.55	461.10
			4,596.55	3,535.10
<b><u>LABOUR</u></b>				
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		450.00	250.00

Report Ref No. CS/LPC20012628/Ktf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.		50.00	20.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		650.00	400.00
			1,150.00	670.00
GRAND TOTAL			5,746.55	4,205.10
RECOMMENDED COST OF REPAIRS				4,205.10

Report Ref No. CS/LPC20012628/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.