

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20012645/QPA3Q2  
**Date:** 18/02/2021

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070116547  
**Claimant**  
**Vehicle No :** SHC4645C **Insured Vehicle No :** GT3843B  
Date of Loss: 10/11/2020 Nature of Claim: TP Claim No: 2974827781SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC4645C**  
Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR1488682  
Reg. Date: 20/01/2015 (Man. Year: 2014) Chassis No: JTDKN36U505756304  
Colour: Maroon Odometer: 734327 km  
Engine Capacity: 1798 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: Neuton 6 mm Rear Left Side: Neuton 6 mm  
Front Right Side: Neuton 6 mm Rear Right Side: Neuton 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,362.80	1,399.48	4,963.32	78.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,832.00	750.00	2,082.00	73.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,194.80</b>	<b>2,149.48</b>	<b>7,045.32</b>	<b>76.62</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,850.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,194.80</b>	<b>1,850.00</b>	<b>7,344.80</b>	<b>79.88</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Car Rental (4.0 x S\$100.58/day) (S\$)</b>		402.32		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>2,459.32</b>		

#### INSPECTION

Date of Assignment: 11/11/2020  
Date Inspected: 11/11/2020 Inspected At: SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705  
Estimated Period of Repair: 3.0 days

**Adjuster:** OI SUN PIN

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Crumpled	458.60 F	*343.95 F
2	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
3	1		*SPOILER REAR (DISC 25%)	Crumpled	953.70 F	*715.28 F
4	1		*3RD BRAKE LAMP (DISC 10%)	Cracked	231.30 F	*208.17 F
5	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
6	1		*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F
7	1		*ARM SUB-ASSY ,RR BUMPER LH	Serviceable	139.60 F	*- F
8	1		*ARM SUB-ASSY ,RR BUMPER RH	Serviceable	139.60 F	*- F
9	1		*ANTENNA,ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
10	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
11	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
12	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
13	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
14	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
15	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
16	1		*UNDER COVER SUBASSY RR FLOOR	Serviceable	514.50 F	*- F
17	1		*TAILGATE ASY	Serviceable	1,007.90 F	*- F
18	1		*TAILGATE OUTSIDE GARNISH	Serviceable	504.90 F	*- F
19	1		*EMBLEM REAR	Serviceable	60.30 F	*- F
20	1		*NAME PLATE (HYBRID)	Serviceable	51.90 F	*- F
21	1		*NAME PLATE (PRIUS)	Serviceable	60.80 F	*- F
22	1		*NAME PLATE (TOYOTA)	Serviceable	51.90 F	*- F
23	1		*SMRT LOGO	Serviceable	7.80 F	*- F
24	1		*STICKER DECAL 6555 8888	Serviceable	21.60 F	*- F
25	1		*3RD BRAKE LAMP	Serviceable	231.30 F	*- F
26	1		*END PANEL	Serviceable	602.10 F	*- F
27	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F

F=Franchise part.

**Total Parts (\$\$)**      **6,362.80**      **1,399.48**

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	676.00	400.00
2	SPRAY PAINT	New	1,476.00	300.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
5	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
6	TO REMOVE AND REFIT WIRE HARDESS	New	200.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,832.00</b>	<b>750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >