

ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396 Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To:

Wee Guan Construction Pte Ltd

Date of report:

04.10.2020

C/o:

7 Sin Ming Industrial Estate Sector C #01-94

Date of request:

03.09.2020

Singapore 575642

Date of inspection:

03.09.2020

Date of accident:

03.09.2020

Report No: AAS/2020/202

Claim type: Third Party Claim

Particulars of affected vehicle:

Registration no:

Odometer:

310365 km

Make/Model:

Isuzu NPR85UH5A (Lorry with hood) Engine Capacity:

2999 cc 4]]11U8945

Year of registration:

2014/15

Multi-Colour

Engine no: Chassis no:

IAANPR85HF7100196

ondition of tires:

Front Left:

Make:

Make:

Colour:

Westlake

Front Right: Make:

Make:

10mm Westlake

Rear Left:

10mm Hankook Rear Right:

10mm Hankook

Type of road wheel:

Alloy

(The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork

: Good : Good

Paintwork Handbrake

: In order

Footbrake

: In order

Steering

: In order

Apparent engine modification

: Nil

The Assignment

The inspection was conduct at M/s.

MJE Motor

7 Sin Ming Industrial Estate Sector C #01-94

Singapore 575642

Assessment

Repairer's estimate:

5,315.00

Revised estimate:

4,495.00

Recommended reserve:

3,600.00 (Lump sum)

Estimated normal duration of repairs: 4 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722 Mobile: 9688-0413 Fax: 6266-7396 Email: absolute.app.svcs@gmail.com

Vehicle No: YN8114H Report No: AAS/2020/202

W/O PREJUDICE

Point of impact

At the rear portion.

General description of damages

The rear wooden gate, rear horizontal plank, rear step plank, rear vertical planks, etc.

Other parts were also found damaged. (See schedule for details)

Lecommendation

The estimate cost of repair submitted by M/s MJE Motor as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$4,495.00

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$3,600.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of $\frac{4}{}$ working days.

'e have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a 'Without Prejudice' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 47 photographs.

Your Faithfully Absolute Appraisal Services Pte Ltd





ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7596 Email: absolute.app.svcs@gmail.com

Vehicle No: YN8114H					Report No: AAS/2020/202			
App	raisement Schedule							
S/N	Parts Description	Qty	Condition		Rej	pairer's Est	Re	vised Est
1	Rear wooden gate with hinges	1	Dented/Cracked		\$	1,200.00	\$	1,200.00
2.	Sticker '60km/h'	1	Necessary		\$	15.00	\$	15.00
3	Sticker '21pax'	1	Necessary		\$	15.00	\$	15.00
4	Rear deck horizontal plank	1	Cracked		\$	150.00	\$	150.00
5	Rear deck vertical plank LH/RH	2	Cracked	\$ 950.00	\$	1,900.00	\$	1,900.00
6	Rear deck step plank	1	Cracked		\$	100.00	\$	100.00
7	Tail lamp RH	1	Cracked		\$	85.00	\$	85.00
<i>(</i>				Special nett total:	 \$	3,465.00	\$	3,465.00
S/N	Labour Description				Rej	pairer's Est	Re	vised Est
1	To lift up wooden deck, replace drear deck.	amage	d wooden planks and	l parts, realign	-	1,800.00	\$	1,000.00
2	Check lightings & wirings.				\$	50.00	\$	30.00
				Labour Total:	\$	1,850.00	\$	1,030.00
ml	final adjusted lump sum amount i		42 600 00	Grand Total:	\$	5,315.00	\$	4,495.00

The final adjusted lump sum amount is \$3,600.00

Under normal circumstances, the repair should be completed within a reasonable period of 4 working days.

47-Photographs were taken at the time of inspection.









