



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 8114H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WOODEN GATE WITH HINGES (SN)	SERVICEABLE	1,200.00	-
1	STICKER '60KM/H' (SN)	NECESSARY	15.00	15.00
1	STICKER '21PAX' (SN)	NECESSARY	15.00	15.00
1	REAR DECK HORIZONTAL PLANK (SN)	SERVICEABLE	150.00	-
2	REAR DECK VERTICAL PLANK LH / RH @\$950.00 (SN)	SERVICEABLE	1,900.00	-
1	REAR DECK STEP PLANK (SN)	SERVICEABLE	100.00	-
1	TAIL LAMP RH (SN)	CRACKED	85.00	85.00
			3,465.00	115.00
	<u>LABOUR</u>			
	TO LIFT UP WOODEN DECK, REPLACE DAMAGED WOODEN PLANKS AND PARTS, REALIGN REAR DECK.		1,800.00	300.00
	CHECK LIGHTINGS & WIRINGS.		50.00	30.00
			1,850.00	330.00
	GRAND TOTAL		5,315.00	445.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			350.00

Report Ref No. CS3/LPC20009444/Gtf3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.