

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012660/BGA3Q2
Date: 16/02/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900021870
Claimant Vehicle No :	SGF7612Z	Insured Vehicle No :	SMG4262T
Date of Loss:	16/11/2020	Nature of Claim:	TP
		Claim No:	5503778039SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGF7612Z	Engine No:	1ZZ2554374
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZNE100303566
Reg. Date:	21/04/2006 (Man. Year: 2006)	Odometer:	442700 km
Colour:	Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Linglong 5 mm	Rear Left Side:	Linglong 5 mm
Front Right Side:	Linglong 5 mm	Rear Right Side:	Linglong 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,933.57	5,707.15	8,226.42	59.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	2,430.00	2,720.00	52.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,083.57	8,137.15	10,946.42	57.36
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	19,083.57	6,500.00	12,583.57	65.94
+ GST 7.00/7.00% (S\$)	1,335.85	455.00	880.85	65.94
Nett Amount (S\$)	20,419.42	6,955.00	13,464.42	65.94
+ Car Rental (9.0 x S\$149.80/day) (S\$)		1,348.20		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		8,339.65		

INSPECTION

Date of Assignment:	17/11/2020		
Date Inspected:	17/11/2020	Inspected At:	160 SIN MING DRIVE#01-14
Estimated Period of Repair:	8.0 days		Repairer: Team Autopro Pte Ltd (Sin Ming)

2/16/2021

Adjuster Report

Adjuster: Lim Teow Guan

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,103.20 FL	*1,103.20 FL
2	1		*TAILGATE LOGO	Necessary	106.30 FL	*76.80 FL
3	1		*TAILGATE INNER TRIM BOARD	Broken	585.20 FL	*485.10 FL
4	1		*TAILGATE OUTER CHROME GARNISH	Broken	262.40 FL	*262.40 FL
5	1		*TAILGATE WEATHERSTRIP	Torn	214.60 FL	*165.00 FL
6	2		*TAILGATE STOPPER	Not Necessary	131.60 FL	*- FL
7	1		*TAILGATE INNER LOCK	Jammed	401.50 FL	*392.00 FL
8	1		*TAILGATE INNER LOCK STICKER	Not Damaged	62.30 FL	*- FL
9	1		*TAILGATE INNER HANDLE	Broken	66.80 FL	*66.80 FL
10	1		*TAILGATE WIPER MOTOR	Not Damaged	468.50 FL	*- FL
11	1		*TAILGATE WINDSCREEN MOULDING	Necessary	287.00 FL	*165.00 FL
12	2		*TAILGATE NUMBER PLATE LAMP	Not Damaged	96.00 FL	*- FL
13	2		*TAILGATE HYDRAULIC DAMPER	Jammed	444.20 FL	*404.00 FL
14	1		*REAR BUMPER	Broken	827.60 FL	*566.10 FL
15	2		*REAR BUMPER SIDE RETAINER	Necessary	228.80 FL	*120.00 FL
16	2		*REAR BUMPER REFLECTOR	Broken	303.60 FL	*150.00 FL
17	2		*REAR BUMPER SUPPORT BRACKET	No such part	274.80 FL	*- FL
18	1		*REAR END PANEL	Dented	748.60 FL	*480.00 FL
19	1		*REAR END PANEL TOP GARNISH	Broken	321.20 FL	*289.00 FL
20	1		*REAR FLOOR PANEL	Not Damaged	1,052.30 FL	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Not Damaged	580.00 FL	*- FL
22	2		*REAR FLOOR PANEL BOARD TOP SIDE BOARD	Not Damaged	636.40 FL	*- FL
23	1		*REAR FLOOR PANEL TOP BOARD REAR GARNISH	Not Damaged	398.00 FL	*- FL
24	2		*REAR FENDER	Repair	1,827.20 FL	*- FL
25	2		*REAR FENDER INNER TRIM BOARD	Broken	1,374.40 FL	*1,230.00 FL
26	2		*REAR FENDER SIDE GLASS MOULDING	Not Necessary	283.00 FL	*- FL
27	1		*SPARE TYRE CARRIER	Not Damaged	245.00 FL	*- FL
28	1		*SPARE TYRE CARRIER BOLT	Not Damaged	45.00 FL	*- FL
29	2		*TAILLAMP	Broken	1,316.60 FL	*760.80 FL
30	1		*EXHAUST PIPE	Repair	910.00 FL	*- FL
31	2		*EXHAUST PIPE MOUNTING	Not Damaged	136.00 FL	*- FL
32	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
33	1		*TAILGATE SEALANT	Necessary	100.00 FS	*60.00 FS
34	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
35	1		*TAILGATE OUTER CHROME MOULDING CLIPS	Necessary	50.00 FS	*30.00 FS
36	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
37	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
38	1		*TAILGATE WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
39	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
40	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
41	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
42	1		*REAR FLOOR PANEL SEALANT	Not Necessary	100.00 FS	*- FS
43	1		*REAR FLOOR PANEL TOP BOARD REAR GARNISH CLIPS	No such part	50.00 FS	*- FS
44	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
45	2		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	100.00 FS	*60.00 FS
46	1		*REAR FENDER SIDE GLASS SEALANT	Not Necessary	100.00 FS	*- FS
47	1		*REAR FENDER SIDE GLASS INNER SEAL	Not Necessary	80.00 FS	*- FS
48	1		*REAR FENDER SIDE GLASS PRIMER & CLEANER	Not Necessary	60.00 FS	*- FS
49	2		*TAILLAMP CLIPS	Necessary	100.00 FS	*40.00 FS
50	2		*TAILLAMP SEAL	Necessary	120.00 FS	*60.00 FS
51	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS

Report was unsubmitted during this print-out.

2/16/2021				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	2		*REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	17,868.10
					7,386.20	
					- List Item Discount on L Items 25.00/25.00% (\$\$)	3,934.53
						1,679.05
					Total Parts (\$\$)	13,933.57
						5,707.15
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REVERSE SENSOR	New	100.00	60.00
4	R&R REAR SIDE GLASS	New	150.00	0.00
5	R&R FUEL TANK PIPE	New	150.00	0.00
6	R&R EXHAUST PIPE	New	150.00	60.00
7	CHECK WIRING	New	100.00	50.00
8	UPHOLSTERY	New	300.00	0.00
9	PANEL BEAT	New	1,800.00	1,000.00
10	RUST PROOFING	New	200.00	60.00
11	SPRAY PAINTING	New	1,800.00	1,000.00
Gross Labour Cost (S\$)			5,150.00	2,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >