

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012669/ATF3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMHCSNA00001942000	
Claimant Vehicle No : SMN4034Z	Insured Vehicle No : SLZ8824H	
Date of Loss: 14/11/2020	Nature of Claim: TP	Claim No: SNM20D204399C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN4034Z		
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Engine No:	L13B3931573
Reg. Date:	06/08/2019 (Man. Year: 2019)	Chassis No:	GK33417083
Colour:	Grey	Odometer:	103243 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,556.88	2,583.20	973.68	27.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	1,990.00	1,100.00	35.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,646.88	4,573.20	2,073.68	31.20
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	6,646.88	3,600.00	3,046.88	45.84
+ GST 7.00/7.00% (S\$)	465.28	252.00	213.28	45.84
Nett Amount (S\$)	7,112.16	3,852.00	3,260.16	45.84

INSPECTION

Date of Assignment:	18/11/2020	
Date Inspected:	18/11/2020	Inspected At: 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B Repairer:Mg Solution (HQ)
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2021)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN4034Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,122.00 FL	*850.00 FL
2	1		*TAIL GATE LOGO	Not Necessary	58.00 FL	*- FL
3	1		*TAIL GATE EMBLEM FIT	Necessary	58.00 FL	*58.00 FL
4	1		*TAIL GATE DETECTOR	Cracked	155.30 FL	*89.00 FL
5	1		*TAIL GATE BUZZEL	Cracked	180.00 FL	*87.00 FL
6	1		*TAIL GATE INNER LOCK	Not Necessary	225.80 FL	*- FL
7	1		*TAIL GATE WEATHER STRIP	Cut	128.00 FL	*128.00 FL
8	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	190.00 FL	*190.00 FL
9	1		*REAR BUMPER	Deformed	730.00 FL	*495.00 FL
10	2		*REAR BUMPER SIDE RETAINER	Necessary	84.00 FL	*84.00 FL
11	1		*REAR BUMPER CENTRE GARNISH	Deformed	230.00 FL	*230.00 FL
12	1		*REAR END PANEL	Deformed	520.00 FL	*378.00 FL
13	1		*REAR END PANEL TOP GARNISH	Cracked	190.00 FL	*190.00 FL
14	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
15	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
16	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
17	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
18	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,331.10	3,139.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	774.22	555.80
Total Parts (\$\$)	3,556.88	2,583.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,200.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
8	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
Gross Labour Cost (\$\$)			3,090.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >