#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EQI20012678/ESD3E2

21/12/2020 Date:

**REFERENCE** 

Handling Insurer: **EQ Insurance Company Ltd** Policy No: DMMPHQ19-001372

**Claimant Vehicle** SH6535S Insured Vehicle No: FBJ969D

No:

15/11/2020 Nature of Claim: TP Claim No: DM20HO01710 Date of Loss:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SH6535S

Make & Model: TOYOTA PRIUS HYBRID, 1.8 (A) Engine No: 2ZR2B84209

Reg. Date: 07/01/2019 (Man. Year: 2018) Chassis No: JTDKB3FU303077765

Colour: Odometer: 0 km Blue

**Engine Capacity:** 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: West Lake 4 mm West Lake 4 mm Front Right Side: West Lake 4 mm Rear Right Side: West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,811.45	3,090.00	721.45	18.93
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,180.00	1,570.00	610.00	27.98
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Gross Total	I (S\$)	5,991.45	4,660.00	1,331.45	22.22
+ GST 7.00/7.00%	s (S\$)	419.40	326.20	93.20	22.22
Nett Amount	t (S\$)	6,410.85	4,986.20	1,424.65	22.22

**INSPECTION** 

Date of Assignment: 18/11/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 18/11/2020 Inspected At: 59 Loyang Drive

Singapore 508969

3.0 days Estimated Period of Repair:

Adjuster: **CHEN TSUE YEE** Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 3 cents - Finalise confirm amount: \$4,808.32

#### **REPAIR DETAILS**

#### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Dec 2020)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SH6535S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR RH	Dented	1,264.00 FL	*1,264.00 FL
2	1		*FRT DOOR DELTA RH	Cut	83.50 FL	*83.50 FL
3	1		*REAR VIEW MIRROR ASSY RH	Broken	1,390.10 FL	*1,373.50 FL
4	1		*REAR VIEW MIRROR OUTER COVER RH	Broken	141.90 FL	*89.50 FL
5	1		*FRT WINDSCREEN PILLAR RH	Repair	343.10 FL	*- FL
6	1		*FRT FENDER RH	Dented	945.30 FL	*945.30 FL
7	1		*FRT FENDER HYBRID EMBLEM RH	Necessary	86.50 FL	*86.50 FL
8	1		*FRT FENDER SHIELD RH	Not Necessary	198.50 FL	*- FL
9	1		*ROCKER PANEL OUTER GARNISH RH	Repair	290.00 FL	*- FL
10	1		*FRT WHEEL HUB CAP RH	Cut	177.70 FL	*177.70 FL
11	1		*FRT DOOR COMFORTDELGRO LOGO RH	Necessary	75.00 F	*75.00 F
12	2		*FRT WINDSCREEN GLASS SEALANT	Not Necessary	46.00 F	*-F
F=Fra	anchise	part. L=ListIte	emDisc.	_		
				Sub Total (S\$)	5,041.60	4,095.00
			- List Item Discount on L Items 25.00/25.00% (S\$)			1,005.00
				Total Parts (S\$)	3,811.45	3,090.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	960.00	800.00
2	SPRAY PAINTING CHARGE	New	800.00	600.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	30.00
5	TRANSFER OF DOOR	New	120.00	50.00
6	REMOVE/REFIX FRT WINDSCREEN GLASS	New	120.00	0.00
7	FRT WHEEL ALIGNMENT	New	80.00	60.00
		Gross Labour Cost (S\$)	2,180.00	1,570.00
	Report was un	submitted during this print-out.		

< END OF ESTIMATES >