

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 3009/11/20

Your Ref: _____

Date: 17th NOV 2020

MR QI JINMING
BLK 880, #09-263
YISHUN STREET 81,
SINGAPORE 760880

Estimate cost of repair to VOLKSWAGON GOLF 1.2 (A) TSI 5 door - SKW 4783 X

1 pc rear bumper	R	\$ 1,036.75 X
10 pcs rear bumper clips	11	60.00 X
1 pc rear bumper reinforcement	17	580.00 X
2 pcs rear bumper o/s & n/s reverse sensor	su	250.00 X
1 pc rear bumper n/s top retainer	17	95.00 X
1 pc rear bumper n/s side retainer	17	105.00 X

Less 10%
\$ 2,126.75
\$ 212.68

\$ 1,914.07

To wiring check up for reverse sensor & necessary parts.

11 40.00 X

To remove & refix carpet, floor mat, garnish & necessary parts, to enable repair rear bumper reinforcement.

11 120.00 X

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear bumper reinforcement & necessary parts, to weld, renew & align above parts.

400.00 200

To respray painting on rear bumper, reinforcement & necessary parts.

450.00 200

\$ 2,924.07

=====

Dollars : Two Thousand Nine Hundred Twenty Four And Cents Seven Only.

HUP MOTOR TRADING & SERVICE

[Signature]

Not Authorized

[Signature]

p/p HOD

2 days.

When the repair

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: