

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20012685/UPS3Q2

Date: 10/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800113504

Claimant
Vehicle No : SLD6376M **Insured Vehicle No :** SLT895L

Date of Loss: 17/11/2020 Nature of Claim: TP Claim No: 3577020124SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD6376M		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZRX572567
Reg. Date:	24/06/2016 (Man. Year: 2016)	Chassis No:	MR053REH104550608
Colour:	Grey	Odometer:	35603 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,461.40	5,859.82	1,601.58	21.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	1,900.00	2,040.00	51.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,401.40	7,759.82	3,641.58	31.94
Approved Total (Overridden) (S\$)		6,200.00		
Nett Amount (S\$)	11,401.40	6,200.00	5,201.40	45.62
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,802.00		

INSPECTION

Date of Assignment: 18/11/2020

Date Inspected: 18/11/2020 Inspected At: Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed/Warped	458.10 FL	*458.10 FL
2	1	*FRONT BUMPER O/S SIDE RETAINER	Cracked	62.90 FL	*62.90 FL
3	1	*FRONT BUMPER CLIPS - 1 SET	Necessary	32.80 FL	*32.80 FL
4	1	*O/S HEADLAMP ASSY	Cracked	2,223.10 FL	*2,223.10 FL
5	1	*FRONT O/S FENDER	Badly Dented	761.50 FL	*761.50 FL
6	1	*FRONT O/S FENDER VVTI EMBLEM	Necessary	39.70 FL	*39.70 FL
7	1	*FRONT O/S FENDER INNER SHIELD	Distorted	236.70 FL	*236.70 FL
8	1	*FRONT O/S FENDER INNER SHIELD CLIPS -1 SET	Necessary	24.00 FL	*24.00 FL
9	1	*FRONT O/S FENDER TOP GARNISH	Not Necessary	89.30 FL	*- FL
10	1	*FRONT O/S DOOR	Badly Dented	1,079.60 FL	*1,079.60 FL
11	1	*FRONT O/S DOOR TOP HINGE	Not Necessary	82.80 FL	*- FL
12	1	*FRONT O/S DOOR LOWER HINGE	Not Necessary	82.80 FL	*- FL
13	1	*FRONT O/S DOOR WEATHERSTRIP	Necessary	157.70 FL	*157.70 FL
14	1	*FRONT O/S DOOR CHECKER	Not Necessary	138.30 FL	*- FL
15	1	*FRONT O/S DOOR GLASS REGULATOR	Not Necessary	268.80 FL	*- FL
16	1	*FRONT O/S DOOR GLASS CHANNEL CASE	Not Necessary	81.70 FL	*- FL
17	1	*FRONT O/S DOOR GLASS CHANNEL	Not Necessary	147.30 FL	*- FL
18	1	*FRONT O/S DOOR FRAME STICKER	Necessary	71.90 FL	*71.90 FL
19	16	*FRONT O/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	4.20 FL	*- FL
20	1	*FRONT O/S SHOCK ABSORBER	Bent	482.90 FL	*482.90 FL
21	1	*FRONT O/S LOWER ARM	Bent	459.30 FL	*459.30 FL
22	1	*FRONT O/S KNUCKLE ARM	Bent	441.40 FL	*441.40 FL
23	1	*FRONT O/S WHEEL BEARING	Necessary	119.40 FL	*119.40 FL
24	1	*FRONT O/S TRADING ARM	Serviceable	180.50 FL	*- FL
25	1	*FRONT O/S SPORT RIM	Cracked	1,394.80 FS	*600.00 FS
26	1	*FRONT O/S WHEEL ABS SENSOR (SPEED)	Shorted	362.10 FL	*362.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,483.60	7,613.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,022.20	1,753.28
Total Parts (\$\$)	7,461.40	5,859.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING	New	150.00	80.00
2	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
3	TO REMOVE & REFIX FRONT O/S DOOR TRIM BOARD, INNER LOCK, HANDLE, GARNISH, GLASS, MOULDING, REGULATOR, MOTOR, CHANNEL, WEATHERSTRIP HINGE,& NECESSARY PARTS INTO NEW DORR	New	200.00	60.00
4	LABOUR CHARGE TO REMOVE & REFIX FRONT O/S SHOCK ABSORBER, LOWER ARM, KUNCKLE ARM, BEARING & NECESSARY PARTS, INCLUDING PUMP THE WHEEL BEARING BY MECHANIC.	New	300.00	120.00
5	TO REMOVE & REFIX CARPET, FLOOR MAT, DOOR PILLAR GARNISH & NECESSARY PARTS, TO ENABLE REPAIR FRONT O/S DOOR PILLAR PANEL & NECESSARY PARTS.	New	100.00	0.00
6	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.	New	90.00	60.00
7	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGES PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT FRONT O/S DOOR PILLAR PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS.	New	1,500.00	600.00
8	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.	New	1,400.00	900.00
9	TO DIAGNOSE & RE-SET ABS (SPEED) SENSOR, USING COMPUTER.	New	150.00	60.00
Gross Labour Cost (\$\$)			3,940.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >