

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20012689/AES3Q2
Date: 14/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100390353
Claimant Vehicle No :	SME177T	Insured Vehicle No :	SJL653J
Date of Loss:	18/11/2020	Nature of Claim:	TP
		Claim No:	6326201782SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME177T		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	CVK068599
Reg. Date:	14/09/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF53JA134014
Colour:	Black	Odometer:	29347 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,809.00	1,828.88	12,980.12	87.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,552.00	2,852.00	3,700.00	56.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,361.00	4,680.88	16,680.12	78.09
+ GST 7.00/7.00% (S\$)	1,495.27	327.66	1,167.61	78.09

Nett Amount (\$\$)	22,856.27	5,008.54	17,847.73	78.09
		+ Loss of Use (5.0 x S\$100.00/day) (\$\$)	500.00	
		+ Doc/Search Fee (\$\$)	7.45	
		Nett Liability (\$\$)	5,515.99	

INSPECTION

Date of Assignment: 20/11/2020

Date Inspected: 20/11/2020

Estimated Period of Repair: 5.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,251.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	402.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	225.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE -LH	Not Necessary	62.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Not Necessary	468.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	36.00 FS	*- FS
8	1		*FRONT FENDER -LH	Dented	1,048.00 FS	*838.40 FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	53.00 FS	*- FS
10	1		*FRONT FENDER CLOSING ELEMENT -LH	Not Necessary	73.00 FS	*- FS
11	1		*FRONT FENDER BRACKET -LH	Not Necessary	35.00 FS	*- FS
12	1		*FRONT FENDER BRACKET -INNER	Not Necessary	35.00 FS	*- FS
13	1		*FRONT FENDER BRACE -LH	Not Necessary	117.00 FS	*- FS
14	1		*WHEEL HOUSING LINER -LH	Not Necessary	272.00 FS	*- FS
15	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
16	1		*WHEEL SOILER	Not Necessary	73.00 FS	*- FS
17	1		*WHEEL SOILER TRIM -LH	Not Necessary	35.00 FS	*- FS
18	1		*STONE CHIP GUARD -LH	Necessary	50.00 FS	*39.92 FS
19	1		*FRONT FENDER TRIM -LH	Necessary	157.00 FS	*125.60 FS
20	1		*TOP FENDER LEDGE COVER -UPPER	Not Necessary	35.00 FS	*- FS
21	1		*TOP FENDER LDGE COVER -LOWER	Not Necessary	16.00 FS	*- FS
22	1		*FRONT ALUMINIUM RIM -LH	Cut	1,012.00 FS	*809.60 FS
23	1		*LED HEADLIGHT -LH	Not Necessary	7,812.00 FS	*- FS
24	1		*BONNET IMPACT PROTECTION -CENTRE	Not Necessary	27.00 FS	*- FS
25	1		*BONNET IMPACT PROTECTION -LH	Not Necessary	28.00 FS	*- FS
26	1		*BONNET IMPACT PROTECTION -RH	Not Necessary	27.00 FS	*- FS
27	1		*SUNDRIES	Necessary	300.00 FS	*15.36 FS
					Total Parts (\$\$)	14,809.00
						1,828.88

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND LHS HEADLIGHT .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER ,LHS FRONT FENDER AND BONNET	New	3,000.00	1,100.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			6,552.00	2,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >