

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20012697/ARS3Q2  
**Date:** 12/04/2021

### REFERENCE

|                                                        |                               |                        |
|--------------------------------------------------------|-------------------------------|------------------------|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No: 2100482808         |                        |
| Claimant Vehicle No : SGV9586T                         | Insured Vehicle No : SLF9353Z |                        |
| Date of Loss: 16/11/2020                               | Nature of Claim: TP           | Claim No: 0423804818SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                                                      |                               |  |
|------------------------------------------------------|-------------------------------|--|
| Reg No: <b>SGV9586T</b>                              |                               |  |
| Make & Model: NISSAN SUNNY, 1.6 EX (M)               | Engine No: QG16426195         |  |
| Reg. Date: 29/06/2007 (Man. Year: 2007)              | Chassis No: JN1CFAN16Z0109709 |  |
| Colour: Maroon                                       | Odometer: 205695 km           |  |
| Engine Capacity: 1597 cc                             |                               |  |
| Market Value/New Car Price: N/A                      |                               |  |
| Sum Insured (S\$): <b>Market Value/New Car Price</b> |                               |  |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                              |                             |                              |
|------------------------------|-----------------------------|------------------------------|
| General Condition:           | Steering (Serviceable): Yes | Footbrake (Serviceable): Yes |
| Handbrake (Serviceable): Yes | Engine Modification: No     | Pre-accident Condition:      |

### CONDITION OF TYRES

|                              |                             |  |
|------------------------------|-----------------------------|--|
| Front Tyre Size: 195/65 R15  | Rear Tyre Size: 195/65 R15  |  |
| Front Left Side: Arivo 6 mm  | Rear Left Side: Arivo 6 mm  |  |
| Front Right Side: Arivo 6 mm | Rear Right Side: Arivo 6 mm |  |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                                  | Repairer's       | Adjuster's      | Difference       | Diff %       |
|-------------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                           | 7,924.10         | 2,180.99        | 5,743.11         | 72.48        |
| Miscellaneous Items                             | 0.00             | 0.00            | 0.00             |              |
| Labour                                          | 4,400.00         | 1,600.00        | 2,800.00         | 63.64        |
| Paintwork Labour                                | 0.00             | 0.00            | 0.00             |              |
| Towing                                          | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>12,324.10</b> | <b>3,780.99</b> | <b>8,543.11</b>  | <b>69.32</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                  | <b>2,300.00</b> |                  |              |
| (S\$)                                           | 12,324.10        | 2,300.00        | 10,024.10        | 81.34        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 862.69           | 161.00          | 701.69           | 81.34        |
| <b>Nett Amount (S\$)</b>                        | <b>13,186.79</b> | <b>2,461.00</b> | <b>10,725.79</b> | <b>81.34</b> |
| <b>+ Loss of Use (7.0 x S\$60.00/day) (S\$)</b> |                  | 420.00          |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 2.00            |                  |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>2,883.00</b> |                  |              |

### INSPECTION

|                                          |                                                                                                             |
|------------------------------------------|-------------------------------------------------------------------------------------------------------------|
| Date of Assignment: 17/11/2020           |                                                                                                             |
| Date Inspected: 17/11/2020 Inspected At: | New Hock Teck Motor Pte Ltd (HQ)<br>1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit<br>Singapore 417883 |
| Estimated Period of Repair: 6.0 days     |                                                                                                             |

---

**Adjuster:** ADRIAN LING**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition     | Repairer's | Amount     |
|-----|-----|----------|----------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *REAR BOOT LID                         | Repair        | 655.00 F   | *- FL      |
| 2   | 1   |          | *REAR BOOT LID CENTER MOULDING         | Not Necessary | 351.00 F   | *- FL      |
| 3   | 1   |          | *REAR BUMPER                           | Deformed      | 433.50 F   | *433.50 FL |
| 4   | 10  |          | *REAR BUMPER CLIPS                     | Necessary     | 65.00 F    | *30.00 FL  |
| 5   | 1   |          | *REAR BUMPER BRACKET                   | N/S Dented    | 183.40 F   | *91.70 FL  |
| 6   | 1   |          | *REAR BUMPER CENTER MOULDING           | Necessary     | 168.60 F   | *168.60 FL |
| 7   | 2   |          | *REAR BUMPER MUD SHIELD                | Not Necessary | 102.40 F   | *- FL      |
| 8   | 8   |          | *REAR BUMPER MUD SHIELD CLIPS          | Not Necessary | 52.00 F    | *- FL      |
| 9   | 2   |          | *REAR BUMPER MUD FLAP                  | Not Necessary | 137.00 F   | *- FL      |
| 10  | 1   |          | *REAR END PANEL                        | Dented        | 376.20 F   | *376.20 FL |
| 11  | 1   |          | *REAR END PANEL TOP GARNISH            | Cracked       | 69.90 F    | *69.90 FL  |
| 12  | 1   |          | *REAR END PANEL TOP GARNISH LOWER TRIM | Crumpled      | 144.20 F   | *144.20 FL |
| 13  | 2   |          | *REAR FENDER                           | Not Necessary | 1,789.60 F | *- FL      |
| 14  | 2   |          | *REAR FENDER INNER TRIM BOARD          | Not Necessary | 484.80 F   | *- FL      |
| 15  | 2   |          | *REAR BOOT LID HINGES                  | Not Necessary | 153.20 F   | *- FL      |
| 16  | 1   |          | *REAR BOOT LID EMBLEM LOGO             | Necessary     | 35.20 F    | *35.20 FL  |
| 17  | 1   |          | *REAR BOOT LID EX SALOON LOGO          | Necessary     | 56.20 F    | *56.20 FL  |
| 18  | 1   |          | *REAR BOOT LID E-THROTTLE LOGO         | Necessary     | 56.20 F    | *56.20 FL  |
| 19  | 1   |          | *REAR BOOT LID SUNNY LOGO              | Necessary     | 77.40 F    | *77.40 FL  |
| 20  | 1   |          | *REAR BOOT LID CVTC LOGO               | Necessary     | 55.10 F    | *55.10 FL  |
| 21  | 2   |          | *REAR BOOT LID CENTER MOULDING CLIPS   | Not Necessary | 13.00 F    | *- FL      |
| 22  | 1   |          | *REAR BOOT LID LOWER MOULDING          | Cut           | 173.80 F   | *173.80 FL |
| 23  | 4   |          | *REAR BOOT LID LOWER MOULDING CLIPS    | Necessary     | 26.00 F    | *10.00 FL  |
| 24  | 1   |          | *REAR BOOT LID INNER LOCK              | Not Necessary | 43.40 F    | *- FL      |
| 25  | 1   |          | *REAR BOOT LID INNER RUBBER            | Cut           | 59.90 F    | *59.90 FL  |
| 26  | 1   |          | *REAR TAIL LAMP                        | Cracked       | 283.20 F   | *283.20 FL |
| 27  | 4   |          | *REAR TAIL LAMP CLIPS                  | Necessary     | 26.00 F    | *26.00 FL  |
| 28  | 2   |          | *REAR BUMPER SIDE RETAINER OUTER       | Necessary     | 54.00 F    | *54.00 FL  |
| 29  | 2   |          | *REAR BUMPER SIDE RETAINER INNER       | Not Necessary | 70.40 F    | *- FL      |
| 30  | 1   |          | *SET REAR BUMPER REVERSE SENSOR        | Damaged       | 350.00 FS  | *200.00 FS |
| 31  | 20  |          | *REAR FENDER INNER TRIM BOARD CLIPS    | Not Necessary | 130.00 F   | *- FL      |
| 32  | 2   |          | *REAR FENDER AIR DUCT                  | Not Necessary | 107.20 F   | *- FL      |
| 33  | 1   |          | *REAR SPARE TYRE PANEL                 | Repair        | 833.50 F   | *- FL      |
| 34  | 1   |          | *REAR SPARE TYRE PANEL TOP COVER       | Not Necessary | 177.70 F   | *- FL      |
| 35  | 1   |          | *REAR WINDSCREEN MOULDING              | Not Necessary | 130.10 F   | *- FL      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                   | <b>7,924.10</b> | <b>2,401.10</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (S\$)</b> | <b>0.00</b>     | <b>220.11</b>   |
| <b>Total Parts (S\$)</b>                                 | <b>7,924.10</b> | <b>2,180.99</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                       | Lab.Type | Repairer's      | Amount          |
|-------------------------|-----------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>     |                                   |          |                 |                 |
| 1                       | TO REMOVE & REFIT CUSHION         | New      | 280.00          | 60.00           |
| 2                       | TO REMOVE & REFIT REVERSE SENSOR  | New      | 100.00          | 50.00           |
| 3                       | TO REMOVE & REFIT REAR WINDSCREEN | New      | 120.00          | 0.00            |
| 4                       | GUM                               | New      | 50.00           | 0.00            |
| 5                       | TO CHECK WIRING                   | New      | 100.00          | 30.00           |
| 6                       | TUFF KOTE                         | New      | 150.00          | 60.00           |
| 7                       | PANEL BEATING                     | New      | 1,800.00        | 600.00          |
| 8                       | SPRAY PAINTING                    | New      | 1,800.00        | 800.00          |
| Gross Labour Cost (S\$) |                                   |          | <b>4,400.00</b> | <b>1,600.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >