

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012698/UVF3E2
Date: 07/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00048312000
Claimant Vehicle No: SMF1808U Insured Vehicle No: GX8558X
Date of Loss: 15/11/2020 Nature of Claim: TP Claim No: SNM20D204414/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF1808U**
Make & Model: NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) Engine No: HR16933034C
Reg. Date: 30/10/2018 (Man. Year: 2018) Chassis No: MNTBBAB17Z0033231
Colour: Red Odometer: 22969 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60R16 Rear Tyre Size: 195/60R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,613.76	1,819.68	794.08	30.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,573.00	1,683.00	890.00	34.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,186.76	3,502.68	1,684.08	32.47
+ GST 7.00/7.00% (S\$)	363.07	245.19	117.88	32.47
Nett Amount (S\$)	5,549.83	3,747.87	1,801.96	32.47

INSPECTION

Date of Assignment: 18/11/2020
Date Inspected: 19/11/2020 Inspected At: Autolution Industrial Pte Ltd (Ubi)
19 Ubi Road 4
Singapore 408623
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED THAT VEHICLE HAS NOT SEND IN FOR REPAIR

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$419.12 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2021)
Parts: 143	NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF1808U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM REAR SYLPHY	Necessary	103.00 FN	*103.00 FN
2	1		*EMBLEM REAR NISSAN	Necessary	54.50 FN	*54.50 FN
3	1		*RH STAY RR BUMPER	Not Necessary	52.00 FN	*- FN
4	1		*LH STAY RR BUMPER	Not Necessary	49.10 FN	*- FN
5	1		*PLATE LUGGAGE REAR GARNISH	Not Necessary	63.90 FN	*- FN
6	2		*TRUNK LID HINGE	Not Necessary	122.60 FN	*- FN
7	1		*TRUNKLID STRIKER	Not Necessary	63.70 FN	*- FN
8	1		*TRUNKLID WEATHERSTRIP	Not Necessary	94.60 FN	*- FN
9	1		*TRUNKLID LOCK	*Check	70.90 FN	*- FN
10	1		*TRUNKLID CHROME GARNISH	Cracked	199.40 FN	*199.40 FN
11	1		*TRUNK LID	Dented	1,250.10 FN	*1,250.10 FN
12	1		*LH SIDE BRACKET RETAINER RR BUMPER	Not Necessary	11.40 FN	*- FN
13	1		*RH SIDE BRACKET RETAINER RR BUMPER	Not Necessary	11.40 FN	*- FN
14	1		*ENERGY ABSORBER RR BUMPER	*Check	78.00 FN	*- FN
15	1		*REAR BUMPER	Deformed	592.60 FN	*592.60 FN
16	1		*SENSOR-REVERSE	*Check	250.00 FS	*- FS
17	1		*SUNDRIES	*Check	50.00 FS	*- FS
18	1		*REAR LICENCE PLATE	Scratched	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	3,177.20	2,259.60
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	563.44	439.92
Total Parts (\$\$)	2,613.76	1,819.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR CHARGES TO REPAIR REAR END PANEL,RENEW TRUNK LID AND REAR BUMPER	New	1,170.00	780.00
2	CHARGES TO SPRAY PAINTING SAME	New	1,000.00	500.00
3	APPLY SEALANT TO TRUNKLID	New	100.00	100.00
4	REMOVE AND INSTALL REVERSE CAMERA	New	120.00	120.00
5	RENEW REVERSE CAMERA	New	55.00	55.00
6	REMOVE AND TRANSFER TRUNK LID MECHANISM	New	80.00	80.00
7	REMOVE AND INSTALL BOTH RR COMB LAMP TO FACILITATE REAR BUMPER REPLACEMENT	New	48.00	48.00
8	SUPPLY REAR LICENSE PLATE (NPA)	New	0.00	0.00
			Gross Labour Cost (\$\$)	2,573.00
				1,683.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >