

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012701/UVD3Q2

Date: 27/11/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00081052003

Claimant Vehicle No : GBG6069C Insured Vehicle No : GBA6527D

Date of Loss: 12/11/2020 Nature of Claim: TP Claim No: SNM20D204365C02/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG6069C**

Make & Model: FIAT DOBLO, 1.6 D CARGO MJ (M) Engine No: 263A50008152821

Reg. Date: 07/09/2017 (Man. Year: 2017) Chassis No: ZFA26300006H18545

Colour: White Odometer: 106604 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/60R16 Rear Tyre Size: 195/60R16

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,090.30	2,379.41	3,710.89	60.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,000.00	500.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,590.30</b>	<b>3,379.41</b>	<b>4,210.89</b>	<b>55.48</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,590.30</b>	<b>2,700.00</b>	<b>4,890.30</b>	<b>64.43</b>

### INSPECTION

Date of Assignment: 17/11/2020

Date Inspected: 18/11/2020 Inspected At: Lius Brother Auto Workshop (HQ)  
Liu's Brother Auto Workshop, Blk 1  
Kaki Bt Ave 6 #01-01 Auto Bay @  
Kaki Bt Singapore 417883  
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 26 Nov 2020)	
<b>Parts:</b>	N/A	FIAT DOBLO 1.6 D CARGO MJ (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG6069C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	745.00 F	*734.34 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	65.00 F	*50.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Distorted	752.00 F	*520.92 FL
4	1		*REAR NUMBER PLATE OUTER GARNISH	Cracked	387.00 F	*387.00 FL
5	1		*REAR LH TAILGATE	Repair	2,395.00 F	*- FL
6	1		*REAR LH TAILGATE WEATHERSTRIP	Not Necessary	344.50 F	*- FL
7	1		*REAR LH TAILGATE MAXI EMBLEM	Necessary	86.00 F	*62.50 FL
8	1		*REAR LH TAILGATE DOBLO EMBLEM	Necessary	118.00 F	*80.20 FL
9	1		*REAR LH TAILGATE 90 EMBLEM	Necessary	97.50 F	*60.00 FL
10	1		*REAR LH TAILGATE MULTIJET EMBLEM	Necessary	119.60 F	*95.00 FL
11	1		*REAR LH TAIL LAMP	Scratched	462.70 F	*420.50 FL
12	1		*REAR LH BUMPER BRACKET	Not Necessary	155.00 F	*- FL
13	1		*REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
14	1		*REAR NUMBER PLATE & BASE	Serviceable	48.00 FS	*- FS
15	1		*REAR LH TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
16	1		*REAR LH TAILGATE SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,090.30</b>	<b>2,620.46</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	241.05
<b>Total Parts (\$\$)</b>	<b>6,090.30</b>	<b>2,379.41</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	0.00
2	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	120.00	50.00
3	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	700.00	400.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	600.00	550.00
<b>Gross Labour Cost (S\$)</b>			<b>1,500.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >