

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012704/KVD3E2

Date: 16/12/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00016982000

Claimant Vehicle
No : GBG4757M

Insured Vehicle
No : YQ2308P

Date of Loss: 12/11/2020

Nature of Claim: TP

Claim
No: SNM20D204426/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG4757M**

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M)

Engine No: 1KD2732722

Reg. Date: 15/08/2017 (Man. Year: 2017)

Chassis No: JTFAT35Y30K208543

Colour: Blue

Odometer: 110434 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8

Rear Tyre Size: 155 R12X8 (D)

Front Left Side: Bridgestone 9 mm

Rear Left Side: Condor 8/8 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Condor 1/1 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	343.80	343.80	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	360.00	180.00	180.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	703.80	523.80	180.00	25.58

INSPECTION

Date of Assignment: 18/11/2020

Date Inspected: 20/11/2020

Inspected At:

Spark Car Care @ Braddell (HQ)
205 BRADDELL RD
Singapore 579701

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Dec 2020)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG4757M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STAINLESS STEEL EXTERNAL DOOR HANDLE	Bent	254.40 FS	*254.40 FS
2	1		*STAINLESS STEEL LOCKING BAR	Distorted	89.40 FS	*89.40 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	343.80
						343.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO CARRY OUT BOX REPAIR, ADJUST & REALIGN DOOR, REPLACE DAMAGED PARTS AND TOUCH UP THE NECESSARY AREAS	New	360.00	180.00
Gross Labour Cost (\$\$)			360.00	180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >