

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20012706/T1CD3E2

**Date:** 27/01/2021

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00125172000

**Claimant Vehicle  
No :** FBQ1533J

**Insured Vehicle  
No :** SLV970S

Date of Loss: 07/11/2020

Nature of Claim: TP

Claim  
No: SNM20D204305/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ1533J**

Make & Model: YAMAHA Y125Z, 124cc

Engine No: E3X6E019087

Reg. Date: 07/08/2019 (Man. Year: 2019)

Chassis No: LBPRES331000019133

Colour: Red

Odometer: 0 km

Engine Capacity: 125 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 2.75/18     | Rear Tyre Size:  | 3.60/18     |
| Front Left Side:  | Shinko 5 mm | Rear Left Side:  | Shinko 5 mm |
| Front Right Side: | 0 mm        | Rear Right Side: | 0 mm        |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                    | 10,623.00         | 6,003.00          | 4,620.00          | 43.49         |
| Miscellaneous Items      | 0.00              | 0.00              | 0.00              |               |
| Labour                   | 930.00            | 280.00            | 650.00            | 69.89         |
| Paintwork Labour         | 0.00              | 0.00              | 0.00              |               |
| Towing                   | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (S\$)</b> | <b>11,553.00</b>  | <b>6,283.00</b>   | <b>5,270.00</b>   | <b>45.62</b>  |

### INSPECTION

Date of Assignment: 18/11/2020

Date Inspected: 18/11/2020 Inspected At:

Hkl Lim Team Motorsport (HQ)  
BLK 1008 #01-24 BUKIT MERAH LANE 3  
Singapore 159722

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)  
(EXCLUDE CHECK ITEMS S\$2,290.00 NETT)

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | (Last Synchronised: 27 Jan 2021)   |  |
| <b>Parts:</b>        | N/A  | YAMAHA Y125Z 124cc (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                    |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for FBQ1533J)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

### Recommended Parts

| No. | Qty | Part No. | Particulars                    | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *LAMP STAY                     | * Check       | 95.00 FS    | *- FS        |
| 2   | 1   |          | *METER ASSY                    | Cracked       | 650.00 FS   | *650.00 FS   |
| 3   | 2   |          | *FRONT FORK ASSY LH / RH       | Bent          | 900.00 FS   | *900.00 FS   |
| 4   | 1   |          | *FRONT FORK UNDER BRACKET      | Bent          | 250.00 FS   | *250.00 FS   |
| 5   | 1   |          | *STEERING CONE BEARING         | Necessary     | 90.00 FS    | *90.00 FS    |
| 6   | 1   |          | *FRONT FORK UPPER CLAM         | * Check       | 120.00 FS   | *- FS        |
| 7   | 1   |          | *BODY FRAME ALIGNMENT          | * Check       | 580.00 FS   | *- FS        |
| 8   | 1   |          | *FRONT FENDER                  | Cracked       | 110.00 FS   | *110.00 FS   |
| 9   | 1   |          | *FRONT FENDER BRACKET          | * Check       | 45.00 FS    | *- FS        |
| 10  | 1   |          | *FRONT WHEEL RIM               | * Check       | 550.00 FS   | *- FS        |
| 11  | 1   |          | *FRONT WHEEL SHALF             | Dented        | 35.00 FS    | *35.00 FS    |
| 12  | 2   |          | *FRONT WHEEL BEARING           | Necessary     | 40.00 FS    | *40.00 FS    |
| 13  | 1   |          | *FRONT WHEEL BEARING OIL SEAL  | Necessary     | 10.00 FS    | *10.00 FS    |
| 14  | 1   |          | *FRONT BRAKE DISC              | * Check       | 220.00 FS   | *- FS        |
| 15  | 1   |          | *FRONT BRAKE CALIPER           | Dented        | 250.00 FS   | *250.00 FS   |
| 16  | 2   |          | *FRONT SIGNALS LH / RH         | Cracked       | 120.00 FS   | *120.00 FS   |
| 17  | 1   |          | *IU UNIT                       | Cut           | 180.00 FS   | *180.00 FS   |
| 18  | 1   |          | *IU UNIT BRACKET               | Not Necessary | 35.00 FS    | *- FS        |
| 19  | 1   |          | *HANDLE BAR                    | Bent          | 120.00 FS   | *120.00 FS   |
| 20  | 1   |          | *HANDLE BAR GRIP               | Not Necessary | 25.00 FS    | *- FS        |
| 21  | 1   |          | *HANDLE BAR BALANCER           | Cut           | 50.00 FS    | *50.00 FS    |
| 22  | 1   |          | *WINDSHIELD                    | Cut           | 80.00 FS    | *80.00 FS    |
| 23  | 1   |          | *FRONT NO PLATE                | Bent          | 12.00 FS    | *12.00 FS    |
| 24  | 1   |          | *BRAKE LEVER                   | Broken        | 35.00 FS    | *35.00 FS    |
| 25  | 1   |          | *CLUTCH LEVER                  | Cut           | 35.00 FS    | *35.00 FS    |
| 26  | 1   |          | *SIDE MIRROR                   | Cut           | 120.00 FS   | *120.00 FS   |
| 27  | 1   |          | *HEADLIGHT                     | Cut           | 250.00 FS   | *250.00 FS   |
| 28  | 1   |          | *HEAD CAWRING CENTER           | Cut           | 80.00 FS    | *80.00 FS    |
| 29  | 1   |          | *HEAD CAWRING LH               | Cut           | 90.00 FS    | *90.00 FS    |
| 30  | 1   |          | *HEAD CAWRING RH               | Cut           | 90.00 FS    | *90.00 FS    |
| 31  | 1   |          | *FRONT BRAKE PUMP              | Not Necessary | 380.00 FS   | *- FS        |
| 32  | 1   |          | *REAR FARK REST RH             | Dented        | 45.00 FS    | *45.00 FS    |
| 33  | 2   |          | *FRONT FARK RECFATOR LH / RH   | Cracked       | 40.00 FS    | *40.00 FS    |
| 34  | 2   |          | *FUEL TANK INNER PANEL LH / RH | Missing       | 160.00 FS   | *160.00 FS   |
| 35  | 2   |          | *FUEL TANK SIDE COVER LH / RH  | Missing       | 360.00 FS   | *360.00 FS   |
| 36  | 1   |          | *GEAR PEDAL                    | Bent          | 70.00 FS    | *70.00 FS    |
| 37  | 1   |          | *BRAKE PEDAL                   | Dented        | 95.00 FS    | *95.00 FS    |
| 38  | 1   |          | *FRONT FOOT REST LH / RH       | Bent          | 180.00 FS   | *180.00 FS   |
| 39  | 1   |          | *FRONT FOOT REST RUBBER        | Torn          | 36.00 FS    | *36.00 FS    |
| 40  | 1   |          | *FUEL TANK                     | Dented        | 1,150.00 FS | *1,150.00 FS |
| 41  | 1   |          | *EXHAUST HEADER-GASKET         | Repair        | 980.00 FS   | *- FS        |
| 42  | 1   |          | *EXHAUST MUFFLER COVER         | Cut           | 90.00 FS    | *90.00 FS    |

| No. | Qty | Part No. | Particulars          | Condition     | Repairer's | Amount     |
|-----|-----|----------|----------------------|---------------|------------|------------|
| 43  | 1   |          | *EXHAUST END CAP     | Cut           | 120.00 FS  | *120.00 FS |
| 44  | 2   |          | *REAR SIGNAL LH / RH | Not Necessary | 120.00 FS  | *- FS      |
| 45  | 1   |          | *REAR WHEEL RIM      | * Check       | 680.00 FS  | *- FS      |
| 46  | 2   |          | *TAILBOARD LH / RH   | Not Necessary | 240.00 FS  | *- FS      |
| 47  | 1   |          | *SIDE STAND          | Dented        | 60.00 FS   | *60.00 FS  |
| 48  | 1   |          | *MAIN STAND          | Not Necessary | 90.00 FS   | *- FS      |
| 49  | 1   |          | *TOP BOX             | Not Necessary | 160.00 FS  | *- FS      |
| 50  | 1   |          | *TOP BOX BRACKET     | Not Necessary | 180.00 FS  | *- FS      |
| 51  | 1   |          | *FRONT BRAKE HOSE    | Not Necessary | 120.00 FS  | *- FS      |

F=Franchise part. S=SpcNett.

|                          |                  |                 |
|--------------------------|------------------|-----------------|
| <b>Total Parts (S\$)</b> | <b>10,623.00</b> | <b>6,003.00</b> |
|--------------------------|------------------|-----------------|

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No                       | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|-------------|----------|------------|--------|
| <u>Labour Items</u>      |             |          |            |        |
| 1                        | LABOUR      | New      | 900.00     | 250.00 |
| 2                        | TOWING      | New      | 30.00      | 30.00  |
| Gross Labour Cost (\$\$) |             |          | 930.00     | 280.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >