

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG20012707/AGS3Q2

Date:

15/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800069585

Claimant Vehicle No : SMM5930K**Insured Vehicle No :**

SMA8246X

Date of Loss: 15/11/2020

Nature of Claim:

TP

Claim No:

5361982343SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMM5930K**

Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)

Engine No: CHZC27825

Reg. Date: 04/07/2019 (Man. Year: 2019)

Chassis No:

WAUZZZ8V3K1025602

Colour: White

Odometer:

24088 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size:

225/40 R18

Front Left Side: 6 mm

Rear Left Side:

6 mm

Front Right Side: 6 mm

Rear Right Side:

6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,613.00	0.00	10,613.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,282.00	2,032.00	3,250.00	61.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,895.00	2,032.00	13,863.00	87.22
+ GST 7.00/7.00% (S\$)	1,112.65	142.24	970.41	87.22

Nett Amount (S\$)	17,007.65	2,174.24	14,833.41	87.22
		+ Loss of Use (4.0 x S\$60.00/day) (S\$)	240.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	2,416.24	

INSPECTION

Date of Assignment: 20/11/2020

Date Inspected: 20/11/2020

Estimated Period of Repair: 4.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,987.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	185.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	38.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	530.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -RH	Not Necessary	293.00 FS	*- FS
6	1		*FRONT BUMPER COVER TRIM -RH	Not Necessary	161.00 FS	*- FS
7	1		*WHEEL HOUSING LINER ADATER RH	Not Necessary	37.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	186.00 FS	*- FS
9	1		*FRONT FENDER -RH	Repair	841.00 FS	*- FS
10	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	71.00 FS	*- FS
11	1		*FRONT FENDER BRACKET -RH	Not Necessary	38.00 FS	*- FS
12	1		*FRONT FENDER BRACE	Not Necessary	95.00 FS	*- FS
13	1		*WHEEL HOUSING LINER -RH	Not Necessary	167.00 FS	*- FS
14	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	88.00 FS	*- FS
15	1		*LED HEADLIGHT -RH	Not Necessary	5,455.00 FS	*- FS
16	1		*LIFT CYLINDER -RH	Not Necessary	141.00 FS	*- FS
17	1		*FRONT ALUMINIUM RIM -RH (NPA)	Not Necessary	0.00 FS	*- FS
18	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	10,613.00	0.00
--------------------------	------------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT ,RE-ORGAISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	240.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,282.00	2,032.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >