

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20012708/ATF3Q2

Date: 19/03/2021

REFERENCE

Insured/Claimant: SONNONTHEE ORAPHIN Policy No: 2070125981
Date of Loss: 08/11/2020 Nature of Claim: OD Claim No: 3118366229SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL9101C**
Make & Model: AUDI Q5, 2.0 TFSI Quattro (A) Engine No: DAX062355
Reg. Date: 28/08/2020 (Man. Year: 2019) Chassis No: WAUZZZF5L2013301
Colour: Grey Odometer: 5570 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$205,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R19 Rear Tyre Size: 235/55R19
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,519.00	1,000.00	17,519.00	94.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,652.00	3,122.00	4,530.00	59.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,171.00	4,122.00	22,049.00	84.25
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	25,171.00	3,122.00	22,049.00	87.60
+ GST 7.00/7.00% (S\$)	1,761.97	218.54	1,543.43	87.60
Nett Amount (S\$)	26,932.97	3,340.54	23,592.43	87.60

INSPECTION

Date of Assignment: 18/11/2020
Date Inspected: 18/11/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,595.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	267.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP-RH	Not Necessary	37.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-RH	Not Necessary	111.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE-CENTRE	Not Necessary	142.00 FS	*- FS
6	1		*FRONT SPOILER	Not Necessary	754.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	474.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	171.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILL-RH	Not Necessary	574.00 FS	*- FS
10	1		*FRONT BUMPER END CAP-RH	Not Necessary	91.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	38.00 FS	*- FS
12	1		*FRONT PARKING AID SENSOR-OUTER	Not Necessary	242.00 FS	*- FS
13	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
14	1		*FRONT FENDER-RH	Repair	1,411.00 FS	*- FS
15	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
16	1		*FRONT FENDER BRACE-RH	Not Necessary	222.00 FS	*- FS
17	1		*FRONT FENDER BRACKET-RH	Not Necessary	17.00 FS	*- FS
18	1		*WHEEL HOUSING LINER-RH	Not Necessary	275.00 FS	*- FS
19	2		*FRONT WHEEL COVER-LH/RH	N/s Necessary/O/s Deformed	1,250.00 FS	*1,000.00 FS
20	1		*LED HEADLIGHT-RH	Not Necessary	7,931.00 FS	*- FS
21	1		*HEADLIGHT MOUNTING-RH	Not Necessary	117.00 FS	*- FS
22	1		*LIFT CYLINDER-RH	Not Necessary	138.00 FS	*- FS
23	1		*FRONT ALUMINIUM RIM-RH	Not Necessary	1,091.00 FS	*- FS
24	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
25	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	38.00 FS	*- FS
26	1		*WHEEL SPOILER-RH	Not Necessary	153.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 18,519.00 1,000.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,400.00	750.00
4	TO RESPRAY FRONT BUMPER,FRONT BUMPER LOWER SPOILER,RHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,900.00	1,700.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,652.00	3,122.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >