

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20012709/ATF3E2

Date: 10/02/2021

REFERENCE

Insured/Claimant:	WAN SOOK YAN, VALERIE	Policy No:	2070097691		
Date of Loss:	13/11/2020	Nature of Claim:	OD	Claim No:	8799326709SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT9160C	Engine No:	CHZC32614
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Chassis No:	WAUZZZ8V9KA117751
Reg. Date:	23/07/2020 (Man. Year: 2019)	Odometer:	4033 km
Colour:	White		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,237.00	2,790.88	4,446.12	61.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,522.00	2,072.00	1,450.00	41.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,759.00	4,862.88	5,896.12	54.80
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	10,159.00	4,262.88	5,896.12	58.04
+ GST 7.00/7.00% (S\$)	711.13	298.40	412.73	58.04
Nett Amount (S\$)	10,870.13	4,561.28	6,308.85	58.04

INSPECTION

Date of Assignment:	18/11/2020		
Date Inspected:	18/11/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	185.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - LOWER CTR	Not Necessary	159.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	530.00 FS	*- FS
5	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	586.00 FS	*- FS
6	2		*FRONT BUMPER TRIM - LH / RH	Not Necessary	322.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cut	1,406.00 FS	*1,124.80 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	189.00 FS	*- FS
9	1		*A/C STICKER	Necessary	8.00 FS	*5.68 FS
10	1		*CAUTION STICKER	Necessary	14.00 FS	*10.80 FS
11	2		*FRONT BUMPER AIR GRILLE - LH / RH	Not Necessary	372.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	715.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT FOAM	Not Necessary	187.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT COVER	Not Necessary	121.00 FS	*- FS
15	1		*FRONT BONNET EDGE PROTECTION	Not Necessary	28.00 FS	*- FS
16	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	48.00 FS	*- FS
17	1		*FRONT BUMPER RADIATOR SUPPORT	Not Necessary	8.00 FS	*- FS
18	1		*FRONT BUMPER AIR GUIDE - UPPER CENTRE	Not Necessary	12.00 FS	*- FS
19	1		*FRONT NO. PLATE	Dented	60.00 FS	*60.00 FS
20	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	7,237.00	2,790.88
-------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTER TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			3,522.00	2,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >