

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20012715/TVF3N2**Date:** 09/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00009682002

Claimant Vehicle No : SMT4428P **Insured Vehicle No :** PA8401D

Date of Loss: 12/11/2020 Nature of Claim: TP Claim No: SNM20D204379C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT4428P**

Make & Model: HONDA SHUTTLE, 1.5 (A) Engine No: L15B6024027

Reg. Date: 12/02/2020 (Man. Year: 2019) Chassis No: GK82103478

Colour: Black Odometer: 34769 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,534.48	4,201.56	2,332.92	35.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,720.00	1,220.00	41.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,474.48	5,921.56	3,552.92	37.50

INSPECTION

Date of Assignment: 18/11/2020

Date Inspected: 19/11/2020 Inspected At: Xinya Auto Services Pte Ltd (HQ)
Blk 1002, #01-75, Bukit Merah Lane 3
Singapore 159719

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Mar 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT4428P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,250.15 FL	*925.70 FL
2	1		*FRONT BUMPER RETAINER RH	Not Necessary	35.40 FL	*- FL
3	1		*FRONT FENDER RH	Bent	485.80 FL	*468.20 FL
4	1		*FRONT FENDER COWLING	Deformed	120.50 FL	*120.50 FL
5	1		*WING MIRROR ASSY RH	Cut	547.55 FL	*547.55 FL
6	1		*FRONT RIGHT DOOR	Dented	1,350.10 FL	*958.20 FL
7	1		*DOOR TAPE SET	Necessary	45.80 FL	*45.80 FL
8	2		*TYRE RIM	Dented	980.30 FL	*980.30 FL
9	1		*STEERING RACK & PINION	Not Necessary	1,748.80 FL	*- FL
10	2		*FRONT ABSORBER	Bent	961.20 FL	*613.80 FL
11	2		*ABSORBER MOUNTING	Bent	71.90 FL	*71.90 FL
12	2		*LOWER ARM	Necessary	570.60 FL	*520.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	8,168.10	5,251.95
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,633.62	1,050.39
Total Parts (\$\$)	6,534.48	4,201.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE FRONT BUMPER,FENDER RH,FRONT RH DOOR & PANEL BEAT & ALIGN	New	1,000.00	600.00
2	TO PUTTY & SPRAY PAINT FRONT BUMPER,FENDER FRONT RH DOOR,WINGMIRROR,AND OTHER AFFECTED AREA	New	800.00	700.00
3	TO TRANSFER FRONT RH DOOR MECHANISM PARTS & GLASS TO NEW DOOR	New	150.00	60.00
4	TO REMOVE & REPLACE STEERING RACK & PINION	New	280.00	0.00
5	TO REPLACE TYRE RIM & TYRE BALANCING	New	80.00	50.00
6	COMPUTERISE WHEEL ALIGNMENT	New	120.00	80.00
7	TUFF KOTE	New	160.00	30.00
8	TO REMOVE & REPLACE UNDERCARRIAGE PARTS (LOWER DOWN CROSSMEMBER)	New	350.00	200.00
			Gross Labour Cost (\$)	1,720.00
				2,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >