

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20012717/QPA3Q2  
**Date:** 12/04/2021

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0006751
<b>Claimant Vehicle No :</b>	SLC5109E	<b>Insured Vehicle No :</b>	SLQ3992K
Date of Loss:	13/11/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002489

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLC5109E</b>		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	2ZR1764441
Reg. Date:	18/05/2016 (Man. Year: 2016)	Chassis No:	JTDGG20WX0J004156
Colour:	Red	Odometer:	59554 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,460.00	1,401.75	2,058.25	59.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	830.00	300.00	26.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,590.00</b>	<b>2,231.75</b>	<b>2,358.25</b>	<b>51.38</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
(S\$)	4,590.00	1,800.00	2,790.00	60.78
<b>+ GST 7.00/7.00% (S\$)</b>	321.30	126.00	195.30	60.78
<b>Nett Amount (S\$)</b>	<b>4,911.30</b>	<b>1,926.00</b>	<b>2,985.30</b>	<b>60.78</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		300.00		
(S\$)		2,226.00		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>1,113.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,120.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,100.00</b>		

### INSPECTION

Date of Assignment:	18/11/2020	Automotive Repair Centre Pte Ltd (HQ)
Date Inspected:	28/12/2020	38 Woodlands Industrial Park E1, #05-18
Inspected At:		Singapore 757700

4/12/2021

Adjuster Report

Estimated Period of Repair: 3.0 days

---

**Adjuster:** OI SUN PIN

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
<b>Parts:</b>	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLC5109E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Crumpled	680.00 F	*569.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*FRONT BUMPER RETAINER LH	Serviceable	80.00 F	*- FL
4	1		*FRONT BUMPER RETAINER RH	Serviceable	80.00 F	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Serviceable	65.00 F	*- FL
6	1		*FRONT REINFORCEMENT	Serviceable	380.00 F	*- FL
7	1		*FRONT SPONGE	Serviceable	120.00 F	*- FL
8	1		*FRONT HEAD LAMP RH	Scratched	1,250.00 F	*1,250.00 FL
9	1		*FRONT FOGLAMP GARNISH RH	Serviceable	75.00 F	*- FL
10	1		*FRONT FENDER RH	Repair	480.00 F	*- FL
11	1		*FRONT FENDER SHIELD RH	Serviceable	150.00 F	*- FL
12	10		*FRONT FENDER CLIPS	Serviceable	50.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,460.00</b>	<b>1,869.00</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	467.25
<b>Total Parts (\$\$)</b>	<b>3,460.00</b>	<b>1,401.75</b>

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINTING (FRONT BUMPER AND FRONT FENDER RH)	New	500.00	400.00
2	REMOVE ,REFIT AND REPAIR AFFECTED ACCIDENT PARTS	New	600.00	400.00
3	CHECK AND RECTIFY ELECTRICAL WIRING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,130.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >