

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG20012727/DVF3N2**Date:** 21/10/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141713MKF
<b>Claimant Vehicle No :</b>	GV4098T	<b>Insured Vehicle No :</b>	SLM3083E
Date of Loss:	18/11/2020	Nature of Claim:	TP
		Claim No:	631098

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GV4098T</b>	Engine No:	4M40DQ0741
Make & Model:	MITSUBISHI FB511B0JRDEB, 2.8 D (M)	Chassis No:	FB511BA42100
Reg. Date:	10/05/2002 (Man. Year: 2002)	Odometer:	72439 km
Colour:	White		
Engine Capacity:	2835 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	165R13C(D)
Front Left Side:	Hankook 5 mm	Rear Left Side:	Yokohama 5/5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Yokohama 5/5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,522.83	3,130.59	9,392.24	75.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,500.00	860.00	6,640.00	88.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>20,022.83</b>	<b>3,990.59</b>	<b>16,032.24</b>	<b>80.07</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,000.00</b>		
<b>(\$\$)</b>	20,022.83	3,000.00	17,022.83	85.02
<b>+ GST 7.00/7.00% (\$\$)</b>	1,401.60	210.00	1,191.60	85.02
<b>Nett Amount (\$\$)</b>	<b>21,424.43</b>	<b>3,210.00</b>	<b>18,214.43</b>	<b>85.02</b>

INSPECTION

Date of Assignment:	18/11/2020	JWG International Pte Ltd (HQ)
Date Inspected:	19/11/2020 Inspected At:	Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
		AutoPoint
		Singapore 568047
Estimated Period of Repair:	4.0 days	

**Adjuster:** BRYAN TANI**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 21 Oct 2021)	
<b>Parts:</b>	N/A	mitsubishi FB511B0JRDEB 2.8 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GV4098T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Dented	1,139.26 FL	*873.00 FL
2	1		*FRONT GRILLE	Cracked	632.24 FL	*568.00 FL
3	1		*FRONT GRILLE MITSUBISHI EMBLEM	Not Necessary	128.75 FL	*- FL
4	2		*HEAD LAMP LH/RH	Cracked/Broken	1,310.04 FL	*1,169.68 FL
5	2		*SIGNAL LAMP LH/RH	Not Necessary	428.68 FL	*- FL
6	2		*SIDE LAMP LH/RH	Not Necessary	357.50 FL	*- FL
7	1		*FRONT BUMPER	Distorted	498.25 FL	*444.40 FL
8	1		*FRONT BUMPER BRACKET O/S	Bent	129.05 FL	*129.05 FL
9	1		*TAIL LAMP LH/RH	O/s Cracked/N/s Not Necessary	499.72 FL	*249.86 FL
10	1		*REAR NO PLATE LAMP	Not Necessary	63.05 FL	*- FL
11	1		*SPARE TYRE BRACKET	Not Necessary	469.23 FL	*- FL
12	1		*SPARE TYRE HOLDER	Not Necessary	25.15 FL	*- FL
13	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
14	1		*FRONT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
15	2		*TAILGATE	Not Necessary	3,200.00 FS	*- FS
16	1		*REAR END PANEL	Not Necessary	1,500.00 FS	*- FS
17	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
18	1		*REAR NO PLATE	Bent	100.00 FS	*20.00 FS
19	4		*TAILGATE HINGE	Not Necessary	1,000.00 FS	*- FS
20	2		*TAILGATE LOCK	Not Necessary	800.00 FS	*- FS
21	2		*TAILGATE CATCH	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>13,090.92</b>	<b>3,473.99</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	568.09	343.40
<b>Total Parts (\$)</b>	<b>12,522.83</b>	<b>3,130.59</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	1,600.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	1,600.00	200.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	New	1,600.00	100.00
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	New	1,600.00	0.00
6	TO TUFF COAT DAMAGED AREAS	New	300.00	30.00
7	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
8	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,500.00</b>	<b>860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >