

ASS. BY:

REF:

CS/MSG20012727/DVJ³

ASSIGNMENT

COB April 2022

From: _____ Date: _____

Veh No:

GV4098T

Yr Regn:

May 2002

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi FB511

C.C. 2835

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

72439

T/Radio: Insured / Std / NI / NA

Eng/No: -

4M40DQ0741

C/No:

FB511 BA42100

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195 R15 C

R: 165 R13 C (double)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Hankook

Rear

Yokohama

R/Bal

5

mm

R/Bal

5/5

mm

L/Bal

5

mm

L/Bal

5/5

mm

D.O.A.

18/11/2020

D.O.L

19/11/2020

Survey held at

JWG AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear y Rear

The U/C / Chassis frame / Body Structure affected due to collision.

OD / ~~TP~~ FWS / TP RES / OD RES / EVA / INV / MV

To Insp Vehicle No: _____

at Work m/s _____

of _____

Insured SLM 3083E

Policy No. 29141713MKF

Claim No. 631098

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Police Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / IR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLura Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

China Teiping SLM 3083E

MV 10K

VIA 6.9K

HL 3.1K

19/10/21. Bryan confirmed LS \$3000 (Red 17,022.83, 85%)

Date/Time, File Pass to?



: Prel. Report

Days Of Repair: 4

1)



: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2) 19/10/21-typist

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Report Format: Merimen

8 FORMS 2001 1 & 2 1/19

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: ~~CHINA TAIPING INSURANCE~~ ^{MSIG} (SINGAPORE) PTE. LTD.
Att: Motor Claims Dept

ACCIDENT INVOLVING SLM3083E [YOUR INSURED] & GV4098T [OUR CLIENT]
ON 18/11/2020.

ESTIMATED REPAIR COSTS FOR GV4098T

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	FRONT PANEL <i>Dented</i>	\$1,139.26 <i>\$873.00</i>	<i>✓</i>
1PC	FRONT GRILLE <i>Crack</i>	\$ 632.24 <i>568.00</i>	<i>✓</i>
1PC	FRONT GRILLE MITSUBISHI EMBLEM <i>NH</i>	\$ 128.75	<i>X</i>
2PCS	HEAD LAMP LH / RH @ \$655.02 EACH <i>Crack / broken 584.84x2</i>	\$ 1,310.04	<i>✓</i>
2PCS	SIGNAL LAMP LH / RH @ \$214.34 EACH <i>NH</i>	\$ 428.68 <i>1169.68</i>	<i>X</i>
2PCS	SIDE LAMP LH / RH @ \$178.75 EACH <i>NH</i>	\$ 357.50	<i>X</i>
1PC	FRONT BUMPER <i>dented</i>	\$ 498.25 <i>444.40</i>	<i>✓</i>
1PC	FRONT BUMPER BRACKET <i>o/s w/t</i>	\$ 129.05	<i>✓</i>
2PCS	TAIL LAMP LH / RH @ \$249.86 EACH <i>o/s crack w/s NH</i>	\$ 499.72	<i>✓</i>
1PC	REAR NO. PLATE LAMP <i>NH</i>	\$ 63.05	<i>X</i>
1PC	SPARE TYRE BRACKET <i>NH</i>	\$ 469.23	<i>X</i>
1PC	SPARE TYRE HOLDER <i>NH</i>	\$ 25.15	<i>X</i>

3433.99

3090.59

PARTS SUM: \$ 5,680.92
PARTS LESS ~~25%~~ *10%*: \$ 1,420.23
PARTS TOTAL: \$ 4,260.69

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY FRONT GRILLE CLIPS <i>NH</i>	\$ 50.00 <i>201</i>
*	TO SUPPLY FRONT PANEL SEALANT <i>NH</i>	\$ 80.00 <i>X</i>
*	TO SUPPLY 2PCS TAILGATE @ \$2,600 EACH <i>NH</i>	\$ 3,200.00 <i>X</i>
*	TO SUPPLY REAR END PANEL <i>NH</i>	\$ 1,500.00 <i>X</i>
*	TO SUPPLY REAR END PANEL SEALANT <i>NH</i>	\$ 80.00 <i>X</i>
*	TO SUPPLY REAR NO. PLATE <i>W/T</i>	\$ 100.00 <i>201</i>
*	TO SUPPLY 4PCS TAILGATE HINGE <i>NH</i>	\$ 1,000.00 <i>X</i>
*	TO SUPPLY 2PCS TAILGATE LOCK <i>NH</i>	\$ 800.00 <i>X</i>
*	TO SUPPLY 2PCS TAILGATE CATCH <i>NH</i>	\$ 600.00 <i>X</i>

40.00

*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00	44
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	\$ 1,600.00	500/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	\$ 1,600.00	200/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	\$ 1,600.00	100/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	\$ 1,600.00	44
*	TO TUFF COAT DAMAGED AREAS	860.00	\$ 300.00 30/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	44

LABOUR & S/N TOTAL: \$ 14,910.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 19,170.69


19/11/2020 @ 11:00am

Not Authorised

Likewise 4 days.

Ryan

LKK Auto



Check MV

Check part prices.

3990.59

L/S 3,000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: