

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20012731/ETF3E2

Date: 27/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070027747
Claimant Vehicle No : FBQ1170Y	Insured Vehicle No :	SMJ1896T
Date of Loss: 13/11/2020	Nature of Claim: TP	Claim No: 3329155577SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ1170Y	Engine No:	G3K5E0090929
Make & Model:	YAMAHA MT-15, 155cc	Chassis No:	ME1RG5913K0007329
Reg. Date:	25/07/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R17	Rear Tyre Size:	140/70 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	18/11/2020	
Date Inspected:	19/11/2020 Inspected At:	149 KAKI BUKIT AVE 1 SOON LEE INDUSTRILA PARK Repairer : Garage 13 Pte Ltd (HQ)
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRONT RIM	Cut	0.00 F	*- F
3	1		*FRONT FENDER WHEEL GUARD	Broken	0.00 F	*- F
4	1		*FRONT BRAKE DISC	Bent	0.00 F	*- F
5	2		*FRONT FORK ASSY	Bent	0.00 F	*- F
6	1		*FRONT FORK BRACKET	Bent	0.00 F	*- F
7	1		*FRONT HEADLAMP RIM	Cut	0.00 F	*- F
8	1		*FRONT HEADLAMP	* Check	0.00 F	*- F
9	1		*FRONT HEADLAMP BRACKET	Bent	0.00 F	*- F
10	2		*FRONT WING MIRROR	Cut	0.00 F	*- F
11	1		*FRONT RH SIGNAL LAMP	Cut	0.00 F	*- F
12	1		*METER ASSY	Cut	0.00 F	*- F
13	1		*STEERING CONE	Necessary	0.00 F	*- F
14	1		*HANDLE BAR	Bent	0.00 F	*- F
15	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
16	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
17	1		*CLUTCH LEVER	Broken	0.00 F	*- F
18	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
19	2		*SIDE FAIRING	Cut	0.00 F	*- F
20	2		*CENTER FAIRING	Cut	0.00 F	*- F
21	1		*FAIRING LOWER	Cut	0.00 F	*- F
22	1		*HELMET	Cut	0.00 F	*- F
23	1		*SEAT BAR, RH	Cut	0.00 F	*- F
24	2		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
25	1		*REAR LH SIGNAL LAMP	Cut	0.00 F	*- F
26	1		*REAR NUMBER PLATE	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >