

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012737/T1VF3Q2

Date: 27/01/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00054982001
Claimant Vehicle No :	SLC7298D	Insured Vehicle No :	SCZ9988T
Date of Loss:	17/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204439/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC7298D		
Make & Model:	PEUGEOT 308, 1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A)	Engine No:	10XT180197486
Reg. Date:	25/05/2016 (Man. Year: 2015)	Chassis No:	VF3LPHNYWFS300511
Colour:	White	Odometer:	95096 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,242.00	11,984.70	1,257.30	9.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	2,110.00	650.00	23.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,002.00	14,094.70	1,907.30	11.92
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	16,002.00	10,000.00	6,002.00	37.51
+ GST 7.00/7.00% (S\$)	1,120.14	700.00	420.14	37.51
Nett Amount (S\$)	17,122.14	10,700.00	6,422.14	37.51

INSPECTION

Date of Assignment:	19/11/2020	
Date Inspected:	19/11/2020 Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jan 2021)
Parts:	144	PEUGEOT 308 1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC7298D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	2,538.00 FL	*2,538.00 FL
2	1		*REAR BOOT LOGO	Necessary	86.00 FL	*86.00 FL
3	1		*REAR BOOT EMBLEM 308	Necessary	84.00 FL	*84.00 FL
4	1		*REAR BOOT EMBLEM PEUGEOT	Necessary	89.00 FL	*89.00 FL
5	1		*REAR BOOT EMBLEM	Necessary	25.00 FL	*25.00 FL
6	1		*REAR BOOT LOCK	Cracked	335.00 FL	*335.00 FL
7	1		*REAR BOOT CATCH	Not Necessary	108.00 FL	*- FL
8	2		*REAR BOOT HINGE L+R	Not Necessary	276.00 FL	*- FL
9	1		*REAR BOOT EMBLEM PURETECH	Necessary	65.00 FL	*65.00 FL
10	1		*REAR BOOT INNER TRIM	Cracked	632.00 FL	*632.00 FL
11	2		*REAR BOOT INNER TRIM L+R	Not Necessary	220.00 FL	*- FL
12	1		*REAR BOOT RUBBER	Twisted	198.00 FL	*198.00 FL
13	1		*REAR BOOT WIPER ARM	Cut	65.00 FL	*65.00 FL
14	1		*REAR BOOT WIPER BLADE	Cut	44.00 FL	*44.00 FL
15	1		*REAR BOOT WIPER MOTOR	Cracked	756.00 FL	*756.00 FL
16	2		*REAR BOOT DAMPLE L+R	Not Necessary	284.00 FL	*- FL
17	2		*REAR BOOT LAMP L+R	Cracked	424.00 FL	*424.00 FL
18	1		*REAR WINDSCREEN GLASS	Cracked	1,256.00 FL	*1,256.00 FL
19	1		*REAR WINDSCREEN MOULDING	Necessary	26.00 FL	*26.00 FL
20	2		*REAR WINDSCREEN SIDE GARNISH L+R	Necessary	288.00 FL	*288.00 FL
21	2		*REAR LAMP L+R	Cracked	596.00 FL	*596.00 FL
22	2		*REAR LAMP CLIPS	Not Necessary	36.00 FL	*- FL
23	1		*REAR BUMPER	Deformed	1,375.00 FL	*1,375.00 FL
24	1		*REAR BUMPER TOW COVER	Deformed	55.00 FL	*55.00 FL
25	1		*REAR BUMPER LOWER GARNISH	Twisted	323.00 FL	*323.00 FL
26	4		*REAR BUMPER SENSOR	Not Working	1,116.00 FL	*1,116.00 FL
27	1		*REAR BUMPER SENSOR WIRE	Torn	481.00 FL	*481.00 FL
28	1		*SET REAR BUMPER SENSOR BRACKET	Necessary	165.00 FL	*165.00 FL
29	1		*REAR BUMPER UNDER COVER	Not Necessary	105.00 FL	*- FL
30	1		*REAR BUMPER REINFORCEMENT	Bent	398.00 FL	*398.00 FL
31	1		*SET REAR BUMPER BRACKET	Deformed	98.00 FL	*98.00 FL
32	1		*SET REAR BUMPER RETAINER	Deformed	88.00 FL	*88.00 FL
33	1		*REAR PANEL	Bent	656.00 FL	*656.00 FL
34	1		*REAR PANEL INNER MEMBER	Not Necessary	368.00 FL	*- FL
35	1		*REAR PANEL INNER TRIM	Deformed	216.00 FL	*216.00 FL
36	1		*REAR PANEL INNER TRIM CLIPS	Necessary	72.00 FL	*72.00 FL
37	1		*REAR FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
38	1		*REAR FLOOR TOP COVER (NPA)	Repair	0.00 FL	*- FL
39	1		*REAR FENDER INNER TRIM L+R (NPA)	Repair	0.00 FL	*- FL
40	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
41	1		*REAR WINDSCREEN FILMMING	Cut	250.00 FS	*250.00 FS
42	1		*REAR NUMBER PLATE	Bent	60.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	2		*BOOT STOPPER L+R	Deformed	56.00 FL	*56.00 FL
44	1		*KEY LESS SENSOR	Cracked	277.00 FL	*277.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					14,670.00	13,273.00
- List Item Discount on L Items 10.00/10.00% (S\$)					1,428.00	1,288.30
Total Parts (S\$)					13,242.00	11,984.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CUT & WELD REAR END PANEL ,TO REPAIR REAR FLOOR PANEL ,REAR FENDER L+R ,REAR CHASSIS MEMBER L+R .TO REMOVE & REFIX DAMAGED PARTS,STRAIGHTEN & REALIGN AFFECTED AREAS	New	1,140.00	800.00
2	TO SPRAY AFFECTED AREAS	New	1,000.00	900.00
3	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	180.00	120.00
4	TO REMOVE & REFIX REAR BOOT MECHANISM ,CHECK & TEST POWER LOCK & WIPER MOTOR	New	80.00	60.00
5	TO REMOVE & REFIX REAR LAGGAGE COMPARTMENT SIDE COVER ,SIDE TRIM BOARD ,CARPET & OTHER ATTACHMENT PARTS	New	100.00	60.00
6	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE	New	60.00	30.00
7	TO RUST PROOF AFFECTED AREAS	New	80.00	40.00
8	TO RESET REAR BOOT FOR FUNCTION	New	120.00	100.00
Gross Labour Cost (\$\$)			2,760.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >