



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDU 9933R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CRACKED	617.50	617.50
2	REAR BUMPER RETAINER @\$15.00	SERVICEABLE	30.00	-
1	REAR BUMPER REINFORCEMENT	BENT	160.00	160.00
2	REAR BUMPER SENSOR @\$145.80	SERVICEABLE	291.60	-
1	REAR BUMPER LOWER GARNISH	DENTED	60.30	60.30
10	REAR BUMPER CLIPS @\$3.50	NECESSARY	35.00	35.00
	LESS 20% DISCOUNT		-238.88	-174.56
			955.52	698.24
	<u>LABOUR</u>			
	TO CHECK REAR WIRING & REPAIR SENSOR.		80.00	50.00
	TO PUTTY & SPRAY PAINT.		300.00	220.00
	LABOUR CHARGES.		250.00	200.00
			630.00	470.00
	GRAND TOTAL		1,585.52	1,168.24
	RECOMMENDED COST OF REPAIRS			1,168.24

Report Ref No. CS/AGI20012739/Ksd3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.