



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : **TP / 19019-10/AY / 2019**
Date of Report : **31 Oct 2019**

Mohd Anuar Bin Md Yusop
No. 9 Elias Green
#01-01
Singapore 519963

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 14 Oct 2019

Workshop Address : M-Tech Motor Services
Blk 9005 Tampines St 93
#01-252
Singapore 528839

As per your instruction dated **18 Oct 2019** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SKP 3560 R**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SKP 3560 R	Engine No	: 27186030291176
Model	: Mercedes Benz E250	Mileage	: 126140
Year / Capacity	: 2013/1796	Colour	: Black
Chassis No	: WDD2120472A482136		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	255/35 R19	Good Year	5.00 mm	Sport
REAR O/S :	255/35 R19	Good Year	5.00 mm	Sport
FRONT N/S :	255/35 R19	Good Year	5.00 mm	Sport
REAR N/S :	255/35 R19	Good Year	5.00 mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 7 working days to complete.
5. Enclosed number of photograph : 162 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SKP 3560 R**
 Report No: **TP/ 19019-10/AY / 2019**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
	<u>Nett Items</u>			
1	Boot lid	Damage	\$ 2850.00	\$ 2850.00
1	Boot lid inner lock	Damage	\$ 320.00	\$ 320.00
1	Boot lid logo	Damage	\$ 78.00	\$ 78.00
1	Boot lid rubber	Necessary	\$ 190.00	\$ 190.00
1	Boot lid 'E250' emblem	Necessary	\$ 85.00	\$ 85.00
1	Boot lid 'AMG' emblem	Necessary	\$ 68.00	\$ 68.00
2	Rear taillamps	Damage	\$ 1440.00	\$ 1440.00
1	Rear end panel	Damage	\$ 1048.00	\$ 1048.00
1	Rear end panel inner garnish	Damage	\$ 152.00	\$ 152.00
1	Rear bumper	Damage	\$ 1680.00	\$ 1680.00
2	Rear bumper lower brackets	Damage	\$ 70.00	\$ 70.00
1	Rear bumper reinforcement	Damage	\$ 850.00	\$ 850.00
2	Rear bumper side retainers	Damage	\$ 96.00	\$ 96.00
1	Rear bumper lower extension	Damage	\$ 395.00	\$ 395.00
1	Rear bumper centre chrome moulding	Necessary	\$ 190.00	\$ 190.00
2	Rear bumper side chrome mouldings	Necessary	\$ 280.00	\$ 280.00
1	Rear bumper inner pad	Damage	\$ 165.00	\$ 165.00
3	Rear bumper reverse sensors	Damage	\$ 858.00	\$ 858.00
2	Rear exhaust silencer chrome tail pipes	Damage	\$ 740.00	\$ 740.00
2	Front headrests	Damage	\$ 1617.00	\$ 1617.00
			<u>\$ 13172.00</u>	<u>\$ 13172.00</u>

Spare Parts Total \$ 13172.00 \$ 13172.00

Vehicle No: **SKP 3560 R**
Report No: **TP/ 19019-10/AY / 2019**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 13172.00	\$ 13172.00
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 100.00	\$ 40.00
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 150.00	\$ 80.00
3	To remove and refit rear bumper sensor.	\$ 120.00	\$ 80.00
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1500.00	\$ 1000.00
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 2000.00	\$ 1500.00
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 90.00
Total		<u>\$ 17192.00</u>	<u>\$ 15962.00</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 12800.00

SDLS: TWELVE THOUSAND EIGHT HUNDRED ONLY


Qualified Appraiser













































































































