

M-TECH MOTOR SERVICES

Blk 9005 Tampine street 93

#01-252 528839

Tel No. : 67840044 Fax No. : 67883025

Buss. Reg. No. : 269252/00B

Mohd Anuar Bin Md Yusop

No. 9 Elias Green

01-01 Singapore 519963

Attention : Motor Claim Department

Final Repair Bill : T1030192

Date : 03/01/2020

Vehicle Num. : SKP 3560 R

Make/Model : Mercedes Benz E250

Chassis/Eng# :

Accident Date : 14/10/2019

Claim No. :

Reference : MT/3560/2019

Policy No. : DMPCSN033591900

Lumpsum Repair

Amount S\$

12,800.00


SingDollars : Twelve Thousand Eight Hundred Only

E. & O.E.

Total S\$:

12,800.00

=====


for M-TECH MOTOR SERVICES

Vehicle No: SKP 3560 R
 Report No: TP/ 19019-10/AY / 2019

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>Nett Items</u>				
1	Boot lid	Damage	\$ 2850.00	\$ 2850.00
1	Boot lid inner lock	Damage	\$ 320.00	\$ 320.00
1	Boot lid logo	Damage	\$ 78.00	\$ 78.00
1	Boot lid rubber	Necessary	\$ 190.00	\$ 190.00
1	Boot lid 'E250' emblem	Necessary	\$ 85.00	\$ 85.00
1	Boot lid 'AMG' emblem	Necessary	\$ 68.00	\$ 68.00
2	Rear taillamps	Damage	\$ 1440.00	\$ 1440.00
1	Rear end panel	Damage	\$ 1048.00	\$ 1048.00
1	Rear end panel inner garnish	Damage	\$ 152.00	\$ 152.00
1	Rear bumper	Damage	\$ 1680.00	\$ 1680.00
2	Rear bumper lower brackets	Damage	\$ 70.00	\$ 70.00
1	Rear bumper reinforcement	Damage	\$ 850.00	\$ 850.00
2	Rear bumper side retainers	Damage	\$ 96.00	\$ 96.00
1	Rear bumper lower extension	Damage	\$ 395.00	\$ 395.00
1	Rear bumper centre chrome moulding	Necessary	\$ 190.00	\$ 190.00
2	Rear bumper side chrome mouldings	Necessary	\$ 280.00	\$ 280.00
1	Rear bumper inner pad	Damage	\$ 165.00	\$ 165.00
3	Rear bumper reverse sensors	Damage	\$ 858.00	\$ 858.00
2	Rear exhaust silencer chrome tail pipes	Damage	\$ 740.00	\$ 740.00
2	Front headrests	Damage	\$ 1617.00	\$ 1617.00
			<u>\$ 13172.00</u>	<u>\$ 13172.00</u>

Spare Parts Total \$ 13172.00 \$ 13172.00

Vehicle No: SKP 3560 R
Report No: TP/ 19019-10/AY / 2019

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 13172.00	\$ 13172.00
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 100.00	\$ 40.00
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 150.00	\$ 80.00
3	To remove and refit rear bumper sensor.	\$ 120.00	\$ 80.00
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1500.00	\$ 1000.00
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 2000.00	\$ 1500.00
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 90.00
Total		<u>\$ 17192.00</u>	<u>\$ 15962.00</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 12800.00

SDLS: TWELVE THOUSAND EIGHT HUNDRED ONLY


Qualified Appraiser