

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20012752/APA3Q2**Date:** 30/03/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100487391   |
| <b>Claimant Vehicle No :</b> | SGZ5507C                             | <b>Insured Vehicle No :</b> | SLH1230L     |
| Date of Loss:                | 16/11/2020                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 0740791961SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | <b>SGZ5507C</b>                   |             |              |
| Make & Model:               | TOYOTA WISH, 1.8 (A)              | Engine No:  | 1ZZ2979946   |
| Reg. Date:                  | 05/11/2007 (Man. Year: 2007)      | Chassis No: | ZNE100384399 |
| Colour:                     | Grey                              | Odometer:   | 256779 km    |
| Engine Capacity:            | 1794 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |              |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/65 R15    | Rear Tyre Size:  | 195/65 R15    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts  | 6,885.57          | 1,584.00          | 5,301.57          | 77.00         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour   | 3,440.00          | 760.00            | 2,680.00          | 77.91         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>              | <b>10,325.57</b>  | <b>2,344.00</b>   | <b>7,981.57</b>   | <b>77.30</b>  |
| <b>Approved Total (Overridden) (S\$)</b>         |                   | <b>1,800.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                         | <b>10,325.57</b>  | <b>1,800.00</b>   | <b>8,525.57</b>   | <b>82.57</b>  |
| <b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b> |                   | 400.00            |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>2,200.00</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>               |                   | <b>2,200.00</b>   |                   |               |

INSPECTION

|                             |                          |   |
|-----------------------------|--------------------------|---|
| Date of Assignment:         | 19/11/2020               |   |
| Date Inspected:             | 23/11/2020 Inspected At: | Ace Autolution Pte Ltd (KAKI BUKIT)<br>13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre<br>Singapore 417807 |
| Estimated Period of Repair: | 4.0 days                 |   |

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's  | Amount     |
|-----|-----|----------|-------------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *FRONT BUMPER                       | Deformed      | 625.00 FL   | *625.00 FL |
| 2   | 1   |          | *FRONT BUMPER SIDE RETAINER LH & RH | N/S Necessary | 110.00 FL   | *55.00 FL  |
| 3   | 2   |          | *FRONT BUMPER FOGLAMP COVER LH & RH | Not Necessary | 190.40 FL   | *- FL      |
| 4   | 1   |          | *FRONT BUMPER LOWER GRILLE          | Not Necessary | 151.20 FL   | *- FL      |
| 5   | 1   |          | *FRONT BUMPER REINFORCEMENT         | Dented        | 425.00 FL   | *302.00 FL |
| 6   | 1   |          | *FRONT BUMPER SPONGE                | Cracked       | 210.00 FL   | *210.00 FL |
| 7   | 1   |          | *FRONT HEADLAMP LH & RH             | N/S Cracked   | 1,760.00 FL | *880.00 FL |
| 8   | 1   |          | *FRONT BONNET                       | Repair        | 1,100.00 FL | *- FL      |
| 9   | 2   |          | *FRONT BONNET HINGE LH & RH         | Not Necessary | 120.00 FL   | *- FL      |
| 10  | 1   |          | *FRONT BONNET INSULATOR             | Not Necessary | 315.00 FL   | *- FL      |
| 11  | 1   |          | *FRONT BONNET LOCK                  | Not Necessary | 93.50 FL    | *- FL      |
| 12  | 1   |          | *FRONT BONNET CHROME                | Not Necessary | 315.00 FL   | *- FL      |
| 13  | 1   |          | *FRONT SUPPORT PANEL COMPLETE       | Not Necessary | 1,530.00 FL | *- FL      |
| 14  | 1   |          | *FRONT BRACE PANEL                  | Not Necessary | 89.00 FL    | *- FL      |
| 15  | 2   |          | *FRONT FENDER LH & RH               | Not Necessary | 1,660.00 FL | *- FL      |
| 16  | 1   |          | *SET FRONT BUMPER CLIPS             | Necessary     | 80.00 FS    | *30.00 FS  |
| 17  | 1   |          | *FENDER SEALANTS                    | Not Necessary | 100.00 FS   | *- FS      |
| 18  | 1   |          | *FRONT FENDER COWLING CLIPS         | Not Necessary | 30.00 FS    | *- FS      |
| 19  | 1   |          | *FRONT FENDER INNER SHIELD CLIPS    | Not Necessary | 80.00 FS    | *- FS      |
| 20  | 1   |          | *FRONT CAR PLATE WITH HOLDER        | Not Necessary | 75.00 FS    | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |          |          |
|---|----------|----------|
| Sub Total (\$)                                    | 9,059.10 | 2,102.00 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 2,173.53 | 518.00   |
| Total Parts (\$)                                  | 6,885.57 | 1,584.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars  | Lab.Type | Repairer's      | Amount        |
|---------------------------------|--|----------|-----------------|---------------|
| <b>Labour Items</b>             |  |          |                 |               |
| 1                               | TO REMOVE AND PANEL BEAT THE AFFECTED PARTS & FITTINGS<br>TO COMMENCE REPAIRS AND REPLACE DAMAGE PARTS | New      | 1,600.00        | 300.00        |
| 2                               | TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY<br>RESPRAY PAINT ON PARTS REPLACED                 | New      | 1,200.00        | 400.00        |
| 3                               | TO REMOVE AND REFIT WIRING AT DAMAGED AREAS  | New      | 250.00          | 30.00         |
| 4                               | TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS   | New      | 240.00          | 30.00         |
| 5                               | TO REMOVE AND REPLACE FRONT HEADLAMP BEAM  | New      | 150.00          | 0.00          |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>3,440.00</b> | <b>760.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >