

(08/11/13) wef

ASS. REC. BY: *marcus*

REF:

CC 4/FC120012755/UBA3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBL 21015

at Workshop m/s

Auto N Car

of

Insured:

SHC 7580k

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$16k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 3406

Vehicle: IN / OUT

Date:

Person Contacted:

Dep 31.

Veh No:

FBL 21015

Yr Regn:

*7, 16*Type: M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha (XSR900) cc 847

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

18768

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*J/ARN 431000003743*Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

120/70ZR17

R:

*180/55ZR19*BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

14/11/20

D.O.I.

20/11/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

1/5, 0/5 Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*repairer spare parts use cost so plus 15%
handle bar replaced**6/1/21 1/5 \$1500 confirmed with Darla*

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

Make: Jaser

not Authorised
Nklr
tel: 62563561
The photo after repair
4 days
20/11/20

1/5 \$1500



Co. Reg: 20135118W
Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883
• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date: 11/19/2020

TO: First Capital Insurance Limited
36 Robinson Road #16-01
City House
Singapore 068877

Total Pages: 1

Our Customer: MUHAMMAD ALFI BIN SHAMSUDIN

Vehicle No: FBL21015

Model: YAMAHA MTM 850A (XSR900)

Manufacture Year: 2016

Date of Accident: 11/14/2020

Total Estimate Repair Days: 7

Attn: Motor Claim Department

Email: cwsmotorclaims@msfirstcapital.com.sg

Re: Repair Estimate For Third Party Claim against: SHC7580K

cost price

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	RH handle grip assembly	1	\$32.00	\$32.00	11X
2	RH handle balancer	1	\$18.50	\$18.50	SCR ✓
3	RH brake handle	1	\$45.80	\$45.80	CU7 ✓
4	Brake wireharness	1	\$35.50	\$35.50	TOR ✓
5	RH side mirror	1	\$135.00	\$135.00	CU7 ✓
6	RH outer absorber fork	1	\$280.00	\$280.00	RX
7	RH front fender bracket	1	\$205.00	\$205.00	RX
8	Radiator side guide	1	\$135.00	\$135.00	RX
9	RH radiator bottom hose	1	\$16.50	\$16.50	11X
10	RH side guide assembly (engine)	1	\$98.00	\$98.00	CU7 ✓
11	RH side guide - block slider assembly	1	\$165.00	\$165.00	CU7 ✓
12	Front exhaust heat shield	1	\$120.00	\$120.00	Bent ✓
13	Rear exhaust heat shield	1	\$110.00	\$110.00	CU7 ✓
14	Front brake padle	1	\$220.00	\$220.00	CU7 ✓
15	RH passenger foot rest bracket	1	\$19.50	\$19.50	SVCX
16	Guide - Stand arm bush assembly	1	\$58.00	\$58.00	11X
17	Brake padle guide	1	\$210.00	\$210.00	CU7 ✓
18	Petrol tank	1	\$367.70	\$367.70	RX
19	Handle bar	1	\$185.50	\$185.50	Bent ✓
	Sub Total			\$2,457.00	
	Cost Plus 15%			\$368.55	
	Sub Total 1			\$2,825.55	
	Total Spare Parts			\$2,825.55	
B.	Labour				
1	Labour to replace handle bar and RH outer absorber fork			\$300.00	200
2	Top up coolant & do pressure test			\$80.00	11X
3	To replace petrol tank			\$80.00	
4	To spray paint petrol tank			\$250.00	200
	Total Labour			\$710.00	
	Total Repair Cost			\$3,535.55	
	* The above quoted are exclusive of GST.				

Surveyor's Details	
Name	
Contact	
Survey Date	

Yours faithfully,

P-1283-30
+ 15%
P-1425-79
L-400.00
1875.79
202
1500.63



Co. Reg: 20135118W

Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883
• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Venessa

f Auto N Cars Services (Commercial) Pte Ltd

Recommend	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: