

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20012758/ABA3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100344996

Claimant
Vehicle No : SLE7301S **Insured Vehicle No :** SJR9724Y

Date of Loss: 18/11/2020 Nature of Claim: TP Claim No: 6187280831SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE7301S		
Make & Model:	MAZDA 3, 1.5 SEDAN L SP.6EAT (A)	Engine No:	P520357318
Reg. Date:	29/07/2016 (Man. Year: 2016)	Chassis No:	JM6BM42A8G0338057
Colour:	Black	Odometer:	63057 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,219.40	4,419.04	3,800.36	46.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,270.00	2,160.00	62.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,649.40	5,689.04	5,960.36	51.16
Approved Total (Overridden) (\$\$)		4,500.00		
(\$\$)	11,649.40	4,500.00	7,149.40	61.37
+ GST 7.00/7.00% (\$\$)	815.46	315.00	500.46	61.37
Nett Amount (\$\$)	12,464.86	4,815.00	7,649.86	61.37
+ Loss of Use (6.0 x S\$80.00/day) (\$\$)		480.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		5,297.00		
Global Sum Settlement (\$\$)		5,290.00		

INSPECTION

Date of Assignment: 19/11/2020

Date Inspected: 19/11/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,157.40 F	*1,157.40 FL
2	1		*REAR BOOT LID EMBLEM LOGO	Necessary	84.40 F	*84.40 FL
3	1		*REAR BOOT LID MAZDA 3 LOGO	Necessary	73.40 F	*73.40 FL
4	1		*REAR BOOT LID SKYACTIVE LOGO	Necessary	83.60 F	*83.60 FL
5	2		*REAR BOOT LID SIDE REFLECTOR	Necessary	790.00 F	*790.00 FL
6	1		*REAR BOOT LID INNER LOCK	Damaged	153.00 F	*153.00 FL
7	1		*REAR BOOT LID INNER RUBBER	Cut	129.30 F	*129.30 FL
8	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	120.20 F	*- FL
9	8		*REAR BOOT LID INNER TRIM BOARD CLIP	Not Necessary	52.00 F	*- FL
10	1		*REAR TAIL LAMP	O/S Cut	1,851.00 F	*925.50 FL
11	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*10.00 FL
12	2		*REAR TAIL LAMP LOWER BRACKET	Not Necessary	138.40 F	*- FL
13	1		*REAR END PANEL	Repair	505.10 F	*- FL
14	1		*REAR END PANEL TOP GARNISH	Deformed	185.10 F	*185.10 FL
15	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	471.20 F	*- FL
16	16		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
17	1		*REAR BUMPER	Deformed	1,049.10 F	*1,049.10 FL
18	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Dented	637.00 F	*537.00 FL
20	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
21	2		*REAR BUMPER TOWING COVER	Not Necessary	41.20 F	*- FL
22	2		*REAR BUMPER SIDE RETAINER	Necessary	66.00 F	*66.00 FL
23	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	64.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,219.40	5,473.80
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,054.76
Total Parts (\$\$)	8,219.40	4,419.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION	New	280.00	50.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO CHECK WIRING	New	100.00	30.00
4	TUFF KOTE	New	150.00	40.00
5	PANEL BEATING	New	1,400.00	500.00
6	SPRAY PAINTING	New	1,400.00	600.00
Gross Labour Cost (\$)			3,430.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >