

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012768/UBS3Q2

Date: 29/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993855

Claimant
Vehicle No : FBM6387C **Insured Vehicle No :** YM6732S

Date of Loss: 18/11/2020 Nature of Claim: TP Claim No: 1914694194SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM6387C	Engine No:	SDH161FMKH3301418
Make & Model:	HONDA CBF 190, 184cc	Chassis No:	LALPJL705H3221822
Reg. Date:	08/01/2018 (Man. Year: 2017)	Odometer:	51675 km
Colour:	White		
Engine Capacity:	184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70-17	Rear Tyre Size:	140/70-17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,399.50	901.00	2,498.50	73.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	410.00	230.00	180.00	43.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,809.50	1,131.00	2,678.50	70.31
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	3,809.50	900.00	2,909.50	76.37
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
Nett Liability (S\$)		960.00		

INSPECTION

Date of Assignment: 19/11/2020

Date Inspected: 20/11/2020 Inspected At:

EROFIA TRADING PTE LTD (HQ)
1 KAKI BUKIT AVE 6 # 02-62
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK	Not Necessary	1,100.00 FL	*- FL
2	1		*FRONT FENDER (MATT BLACK)	Not Necessary	90.00 FL	*- FL
3	1		*FRONT LAMP SIDE COVER (RED) -L/H	Not Necessary	45.00 FL	*- FL
4	1		*FRONT FAIRING	Not Necessary	165.00 FL	*- FL
5	1		*ENGINE GUARD	Repair	220.00 FL	*- FL
6	1		*HANDLE PROTECTOR	Scratched	120.00 FL	*120.00 FL
7	1		*MIRROR-L/H	Cut	55.00 FL	*55.00 FL
8	1		*HANDLE BAR	Serviceable	90.00 FL	*- FL
9	1		*FRONT SIGNAL -L/H	Not Necessary	120.00 FL	*- FL
10	1		*FRONT BRAKE DISC	Not Necessary	200.00 FL	*- FL
11	1		*LOWER BELLY	Not Necessary	160.00 FL	*- FL
12	1		*RIDER FOOT REST-L/H	Cut	35.00 FL	*35.00 FL
13	1		*RIDER FOOT REST BRACKET-L/H	Cut	120.00 FL	*120.00 FL
14	1		*PILLION FOOT REST -L/H	Cut	35.00 FL	*35.00 FL
15	1		*PILLION FOOT REST BRACKET-L/H	Not Necessary	85.00 FL	*- FL
16	1		*SIDE STAND	Repair	40.00 FL	*- FL
17	1		*GEAR PEDAL	Not Necessary	40.00 FL	*- FL
18	1		*CHAIN COVER	Cracked	65.00 FL	*65.00 FL
19	1		*BEARING CONE	Not Necessary	85.00 FS	*- FS
20	1		*REAR NUMBER PLATE	Bent	28.00 FS	*14.00 FS
21	1		*E.R.P IU	Not Necessary	200.00 FS	*- FS
22	1		*REAR BOX	Cracked	580.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,678.00	944.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	278.50	43.00
Total Parts (\$\$)	3,399.50	901.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING	New	60.00	0.00
2	TO PROVIDE LABOUR	New	350.00	230.00
Gross Labour Cost (\$)			410.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >