

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20012771/USD3Q2

Date: 01/12/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001287492

Claimant
Vehicle No : SKH8413S

Insured Vehicle No : YL1643D

Date of Loss: 16/11/2020

Nature of Claim: TP

Claim No: 249856

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKH8413S**

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2429671

Reg. Date: 03/01/2006 (Man. Year: 2005)

Chassis No: ZNE100277572

Colour: Silver

Odometer: 503691 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17

Rear Tyre Size: 215/45R17

Front Left Side: Sumitomo 5 mm

Rear Left Side: KAPSEN 5 mm

Front Right Side: Sumitomo 5 mm

Rear Right Side: KAPSEN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,114.30	764.02	4,350.28	85.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,100.00	970.00	46.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,184.30	1,864.02	5,320.28	74.05
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	7,184.30	1,000.00	6,184.30	86.08
+ GST 7.00/7.00% (S\$)	502.90	70.00	432.90	86.08
Nett Amount (S\$)	7,687.20	1,070.00	6,617.20	86.08

INSPECTION

Date of Assignment: 19/11/2020

Date Inspected: 20/11/2020 Inspected At:

Focus Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #02-48/50 Autobay

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2020)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH8413S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Badly Dented	654.20 FL	*588.10 FL
2	1		*FRONT FENDER DUST COVER RH	Not Necessary	189.40 FL	*- FL
3	6		*FRONT FENDER DUST COVER CLIPSE RH	Not Necessary	33.00 FL	*- FL
4	1		*FRONT FENDER LAMP RH	Broken	35.20 FL	*32.20 FL
5	1		*FRONT HEAD LAMP RH	Serviceable	864.40 FL	*- FL
6	1		*FRONT BUMPER	Repair	687.50 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	68.20 FL	*- FL
8	1		*FRONT RH 1/4 GLASS	Serviceable	289.40 FL	*- FL
9	1		*FRONT DOOR RH	Repair	958.60 FL	*- FL
10	1		*FRONT DOOR SIDE MIRROR RH	Broken	398.40 FL	*398.40 FL
11	1		*FRONT DOOR HINGE TOP RH	Not Necessary	48.20 FL	*- FL
12	1		*FRONT DOOR RUBBER RH	Not Necessary	289.40 FL	*- FL
13	1		*FRONT SHOCK ABSORBER RH	Not Necessary	389.40 FL	*- FL
14	1		*FRONT KNUCKLE ARM RH	Not Necessary	316.40 FL	*- FL
15	1		*FRONT HUB BEARING RH	Not Necessary	276.20 FL	*- FL
16	1		*FRONT LOWER ARM RH	Not Necessary	374.50 FL	*- FL
17	1		*FRONT DOOR VISOR RH	Not Necessary	60.00 FS	*- FS
18	1		*FRONT SPORT RIM RH	Repair	650.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,582.40	1,018.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,468.10	254.68
Total Parts (\$\$)	5,114.30	764.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	850.00	400.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	30.00
4	ALIGNMENT	New	50.00	50.00
5	TO REMOVE & REPLACE FRONT UNDER CARRIAGE	New	250.00	0.00
6	TO SPRAY PAINTING	New	800.00	600.00
Gross Labour Cost (\$)			2,070.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >