

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/FWD19018054/QQF3E2-1  
**Date:** 20/11/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd.	Policy No: PNPV2019-00009274	
Claimant Vehicle No : GBG7126P	Insured Vehicle No : SLQ5089E	
Date of Loss: 11/10/2019	Nature of Claim: TP	Claim No: 1201900030634

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG7126P	Engine No:	1KD2754191
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Chassis No:	JTFHT02P500234551
Reg. Date:	13/10/2017 (Man. Year: 2017)	Odometer:	88346 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bearway 5 mm	Rear Left Side:	Bearway 5 mm
Front Right Side:	Bearway 5 mm	Rear Right Side:	Bearway 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,866.72	2,928.45	1,938.27	39.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,945.00	1,527.50	417.50	21.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,811.72</b>	<b>4,455.95</b>	<b>2,355.77</b>	<b>34.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,550.00</b>		
<b>(S\$)</b>	6,811.72	3,550.00	3,261.72	47.88
<b>+ GST 7.00/7.00% (S\$)</b>	476.82	248.50	228.32	47.88
<b>Nett Amount (S\$)</b>	<b>7,288.54</b>	<b>3,798.50</b>	<b>3,490.04</b>	<b>47.88</b>

### INSPECTION

Date of Assignment:	14/04/2020	
Date Inspected:	15/10/2019	Inspected At:
		Hui Wang Enterprise Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-576 Singapore 539187
Estimated Period of Repair:	5.0 days	

**Adjuster:** OI SUN PIN

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2020)
<b>Parts:</b>	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG7126P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	2,154.00 FL	*1,850.00 FL
2	1		*TAIL GATE INNER TRIM	Serviceable	325.80 FL	*- FL
3	1		*TAIL GATE INNER LOCK	Jammed	341.20 FL	*341.20 FL
4	1		*TAIL GATE OUTER GARNISH	Serviceable	185.90 FL	*- FL
5	1		*TAIL GATE LOGO	Necessary	63.70 FL	*63.70 FL
6	1		*TAIL GATE WEATHERSTRIP	Broken	215.80 FL	*215.80 FL
7	1		*TAIL GATE EMBLEM HIACE	Necessary	48.90 FL	*48.90 FL
8	1		*REAR BUMPER	Deformed	498.50 FL	*498.50 FL
9	1		*REAR BUMPER SIDE RETAINER	N/S Broken	130.40 FL	*65.20 FL
10	1		*REAR TAIL LAMP LH	Cracked	265.50 FL	*265.50 FL
11	1		*REAR TAIL LAMP LOWER GARNISH	Deformed	115.80 FL	*115.80 FL
12	1		*REAR TAIL LAMP LOWER GARNISH BRACKET LH	Serviceable	41.90 FL	*- FL
13	1		*REAR END PANEL OUTER	Repair	750.60 FL	*- FL
14	1		*REAR END PANEL INNER	Repair	445.80 FL	*- FL
15	1		*REAR SPARE TYRE BRACKET	Serviceable	398.50 FL	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
17	1		*TAIL GATE STICKER 8 PAX	Necessary	20.00 FS	*20.00 FS
18	1		*TAIL GATE STICKER 70KM/H	Necessary	20.00 FS	*20.00 FS
19	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
20	1		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,362.30</b>	<b>3,794.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,495.58	866.15
<b>Total Parts (\$\$)</b>	<b>4,866.72</b>	<b>2,928.45</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	990.00	650.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIALS	New	600.00	600.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	40.00	40.00
4	WIRING AND BULB CHECKING	New	22.50	22.50
5	REMOVE AND REFIX TAILGATE REAR WINDSCREEN GLASS (2-MAN JOB)	New	135.00	135.00
6	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	76.50	30.00
7	TRANSFER OF EXISTING TAILGATE MECHANISM TO NEW TAILGATE	New	81.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,945.00</b>	<b>1,527.50</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >