

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012778/R1QF3E2

Date: 04/05/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00153732000	
Claimant Vehicle No :	FBA8012J	Insured Vehicle No :	SGV7088C	
Date of Loss:	13/11/2020	Nature of Claim:	TP	Claim No: SNM20D204457/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBA8012J	Engine No:	T713126891
Make & Model:	SUZUKI GSX-R 1000, 988cc (M)	Chassis No:	JS1B6111100109165
Reg. Date:	02/09/2006 (Man. Year: 2005)	Odometer:	68550 km
Colour:	Multi-colour		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 ZR17	Rear Tyre Size:	190/55 ZR17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,120.00	6,231.50	8,888.50	58.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,050.00	1,150.00	52.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,320.00	7,281.50	10,038.50	57.96
Approved Total (Overridden) (\$\$)		4,500.00		
Nett Amount (\$\$)	17,320.00	4,500.00	12,820.00	74.02

INSPECTION

Date of Assignment:	20/11/2020		
Date Inspected:	20/11/2020	Inspected At:	Hkl Lim Team Motorsport (HQ) BLK 1008 #01-24 BUKIT MERAH LANE 3 Singapore 159722
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 May 2021)	
Parts:	N/A	SUZUKI GSX-R 1000 988cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBA8012J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK ASSY LH / RH	Serviceable	2,400.00 F	*- FL
2	1		*FRONT FORK UNDER BRACKET	Serviceable	680.00 F	*- FL
3	1		*STEERING CONE BEARING	Serviceable	150.00 F	*- FL
4	1		*FRONT FENDER	Serviceable	250.00 F	*- FL
5	1		*FRONT WHEEL RIM	Repair	750.00 F	*- FL
6	2		*FRONT BRAKE DISC LH / RH	Serviceable	800.00 F	*- FL
7	1		*HANDLE BAR RH	Serviceable	220.00 F	*- FL
8	1		*HANDLE BAR BALANCER	Scratched	120.00 F	*120.00 FL
9	1		*BRAKE PUMP FREMBO	Scratched	750.00 F	*750.00 FL
10	1		*TAIL BOARD CENTER	Cracked	280.00 F	*280.00 FL
11	1		*TAIL BOARD LH	Cracked	190.00 F	*190.00 FL
12	1		*TAIL BOARD RH	Cracked	190.00 F	*190.00 FL
13	1		*RIDER SEAT	Serviceable	220.00 F	*- FL
14	1		*PILLIAN SEAT	Torn	230.00 F	*230.00 FL
15	1		*PILLIAN SEAT LOCK	Cracked	120.00 F	*120.00 FL
16	1		*PILLIAN SEAT LOCK CABLE	Serviceable	55.00 F	*- FL
17	1		*PILLIAN SEAT LOCK (KEY)	Serviceable	95.00 F	*- FL
18	1		*REAR FENDER	Serviceable	120.00 F	*- FL
19	1		*REAR NO PLATE LIGHT	Serviceable	95.00 F	*- FL
20	2		*TAIL SHALF FRAME LH / RH	Cracked	900.00 F	*900.00 FL
21	2		*TAIL SHALF FRAME BRACKET	Necessary	110.00 F	*110.00 FL
22	1		*REAR FOOT REST / BRACKET RH	Scratched	195.00 F	*195.00 FL
23	1		*TAIL SHALF FRAME CENTER	Repair	450.00 F	*- FL
24	1		*BRAKE PEDAL	Scratched	120.00 F	*120.00 FL
25	1		*FRONT FOOT REST RH	Scratched	95.00 F	*95.00 FL
26	1		*FRONT FOOT REST BRACKET RH	Serviceable	120.00 F	*- FL
27	1		*FUEL TANK	Serviceable	1,800.00 F	*- FL
28	1		*EXHAUST INSPRETION	Necessary	80.00 FS	*80.00 FS
29	1		*EXHAUST MUFFLER	Cracked	1,200.00 F	*1,200.00 FL
30	1		*REAR SIGNAL LH / RH	Scratched	240.00 F	*240.00 FL
31	1		*TAIL LIGHT	Broken	220.00 F	*220.00 FL
32	1		*SIDE FAIRING RH INNER	Cracked	750.00 F	*750.00 FL
33	2		*SIDE FAIRING LH / RH OUTER	Cracked	420.00 F	*420.00 FL
34	1		*FRAME SLIDER	Scratched	150.00 F	*150.00 FL
35	1		*TOOL PANEL	Cracked	95.00 F	*95.00 FL
36	2		*FUEL TANK PANEL LH / RH	Cracked	240.00 F	*240.00 FL
37	1		*REAR FENDER LONG PLATE	Cracked	220.00 F	*220.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,120.00	6,915.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	683.50
Total Parts (\$\$)	15,120.00	6,231.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	1,200.00	600.00
2	LABOUR	New	950.00	400.00
3	TOWING	New	50.00	50.00
Gross Labour Cost (\$)			2,200.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >